





General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Grey
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 сс
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	Κ







Internet history


Entry 2

Date Pictures 2023-01-29

33

Listing price

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

2021-07-01

39

Listing price


View report



source: cargurus.co.uk









MOT history

MOT expiry date	2025-02-15
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	12
Total items failed	6

MOT #11	2024-02-13 09:14
MOT test number	681598292208
Result	✓ Passed
Next expiry date	2025-02-15

MOT #10	2023-02-16 12:57
MOT test number	181783537252
Result	✓ Passed

MOT #9		2022-07-18 10:09
MOT test	number	749597862766
Result		✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Inner Tyre slightly damaged sidewall split (5.2.3 (d) (ii))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread $(0.1 (b))$	





2020-07-22 10:16 727617430335

MOT #8		2021-07-20 12:16
MOT test	number	884100993040
Result		✓ Passed
Advice	Nearside Rear tyre worn and cracked far outer edge	
Advice	Offside Rear tyre 3mm	

MOT #7

мот	test	number	
-----	------	--------	--

Result	✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2019-08-08 10:06
MOT test number	722532752197
Result	✓ Passed

MOT #5	2018-08-13 13:24
MOT test number	194149453022
Result	✓ Passed
MOT #4	2017-07-18 14:41
MOT test number	705165612966
Result	✓ Passed

MOT #3	2016-07-25 09:44
MOT test number	317832042213
Result	✓ Passed





MOT #2		2015-07-01 15:02
MOT test number		169682385141
Result		✓ Passed
MOT #1		2015-07-01 12:46
MOT test number		496092185132
Result		× Failed
Fail Nearside Registrat	tion plate lamp not working (1.1.C.1d)	
Fail Offside Headlamp	aim too high (1.8)	
Fail Windscreen washe	er provides insufficient washer liquid (8.2.3)	
Fail Offside Front posit	tion lamp(s) not working (1.1.A.3b)	
Fail Offside Registratio	on plate lamp not working (1.1.C.1d)	
Fail Nearside Headlam	np not working on dipped beam (1.7.5a)	



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	✓ MOT Expires: 15 February 2025
Tax status	Valid until 1 February
Days left	278
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	LAMP
Туре	
Damage 2	AMPLE
Date	F Store 1
Date	OLE
Category	AM
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

AND	

NUMBER OF CONTRACTOR OF CONTRA	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-07-25
Last registration	2024-02-13
Complete history	See info



Registration #1	2012-07-25	28 mi
Registration #2	2015-07-01	8.992 mi
Registration #3	2015-07-01	8.992 mi
Registration #4	2016-07-25	9.158 mi
Registration #5	2017-07-18	12.038 mi
Registration #6	2018-08-13	15.611 mi
Registration #7	2019-08-08	17.707 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		
		11.777 esi
Registration #13		11.777 es





Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg
Additional information	
Additional information Fuel tank capacity	65 l
	65 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5