



**GU6IGZS**

report date: 2024-03-29

General information

Make	MAZDA
Model	5 D SPORT
Colour	Black
Year of manufacture	2011
Top speed	111 mph
0 - 60 mph	13.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-14
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2025-01-10
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	36
Total items failed	2

MOT #11	2024-01-11 14:47
MOT test number	992767661548
Result	✓ Passed
Next expiry date	2025-01-10
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10	2024-01-11 12:47
MOT test number	604313963331
Result	✗ Failed
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #9	2022-12-12 10:48
MOT test number	566048868623
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Undertrays fitted

**MOT #8**

2021-12-13 12:25

**MOT test number**

616795360461

**Result**

✓ Passed

**Advice**

Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))

**MOT #7**

2020-11-23 12:49

**MOT test number**

223773385903

**Result**

✓ Passed

**Advice**

Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice**

Exhaust heat shield insecure around fuel tank

**MOT #6**

2019-12-09 13:54

**MOT test number**

891925420158

**Result**

✓ Passed

**Advice**

Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice**

Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Rear Exhaust heat shield loose/insecure

**Minor**

Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice**

Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Rear wiper split

**Minor**

Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #5**

2018-11-21 17:07

**MOT test number**

553480386107

**Result**

✓ Passed

- Advice** Offside Front Lower Suspension arm ball joint has slight play advise replacement (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #4**

2017-12-06 16:58

**MOT test number**

375468260599

**Result**

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Anti-roll bar linkage has slight play in a ball joint nearside/offside rear lower (2.4.G.2)
- Advice** Vehicle undercovers fitted covering testable components
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front wiper blade end worn /still clearing screen
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #3**

2016-12-12 13:35

**MOT test number**

277000724092

**Result**

✓ Passed



MOT #2	2015-10-03 08:57
MOT test number	232042388297
Result	✓ Passed
Advice	Child seats fitted

MOT #1	2014-10-11 09:40
MOT test number	969154984256
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
10 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	10 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-12-08
Last registration	2024-01-11
Complete history	<a href="#">See info</a>



Registration #1	2011-12-08	27 mi
Registration #2	2014-10-11	31.374 mi
Registration #3	2015-10-03	42.269 mi
Registration #4	2016-12-12	47.568 mi
Registration #5	2017-12-06	57.068 mi
Registration #6	2018-11-21	66.880 mi
Registration #7	2019-12-09	77.556 mi
Registration #8	2020-05-20	85.277 mi
Registration #9	2020-05-20	85.277 mi
Registration #10	2020-05-20	85.277 mi
Registration #11	2020-05-20	85.277 mi
Registration #12	2020-05-20	85.277 mi
Registration #13	2020-05-20	85.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1490 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Indirect Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	Y6 325182