



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO
Colour	Grey
Year of manufacture	2004
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	117 BHP
Max. torque	159 Nm at 4.000 rpm
Engine capacity	1.749 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-09-14
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-15
MOT pass rate	86 %
MOT passed	19
Failed MOT tests	3
Total advice items	19
Total items failed	8

MOT #22	2024-03-01 09:52
MOT test number	600215296018
Result	✓ Passed
Next expiry date	2025-03-15
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #21	2023-02-25 09:31
MOT test number	576287686278
Result	✓ Passed

MOT #20	2022-02-26 09:27
MOT test number	486331610309
Result	✓ Passed

MOT #19	2021-03-10 11:31
MOT test number	958210377323
Result	✓ Passed
Advice	Play in steering rack inner joint(s)
Advice	Tyre worn close to legal limit/worn on edge both sides front (5.2.3 (e))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #18** 2020-03-09 10:39**MOT test number** 761566406995**Result** ✓ Passed**Advice** Nearside front constant velocity joint boot slight leak of grease**Advice** Brake hose slightly deteriorated both sides rear (1.1.12 (b) (ii))**Advice** Play in steering rack inner joint(s)**MOT #17** 2019-02-27 11:10**MOT test number** 829633142958**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge +uneven wear (5.2.3 (e))**Advice** Exhaust mounting corroded and deteriorated system slightly insecure**MOT #16** 2018-03-16 17:41**MOT test number** 473037111553**Result** ✓ Passed**MOT #15** 2017-06-26 11:04**MOT test number** 978677691873**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Power steering component(s) has slight seepage from a component PAS pressure switch. (2.3.3b)

**MOT #14**

2017-06-26 11:04

MOT test number

738997686232

Result**✗ Failed****Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Power steering component(s) has slight seepage from a component PAS pressure switch. (2.3.3b)**Pass with rectification** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #13**

2016-06-27 15:59

MOT test number

872470379346

Result**✓ Passed****Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #12**

2016-06-27 15:59

MOT test number

527583566333

Result**✗ Failed****Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front wheel bearing rough when rotated (2.5.A.2)**MOT #11**

2015-06-01 14:37

MOT test number

599852755139

Result**✓ Passed**



MOT #10	2014-06-23 15:55
----------------	------------------

MOT test number	266934974468
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2013-06-12 15:31
---------------	------------------

MOT test number	918403763128
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2012-06-12 11:45
---------------	------------------

MOT test number	487434762164
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2011-07-01 15:22
---------------	------------------

MOT test number	615752981143
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2011-07-01 15:22
---------------	------------------

MOT test number	637402981174
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
--------------------------------	-------------------------------------------------------------------------------------

MOT #5	2010-08-24 12:36
---------------	------------------

MOT test number	852416130242
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-08-26 09:44
---------------	------------------

MOT test number	823718539299
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #3	2008-08-20 11:13
MOT test number	831123538224
Result	✓ Passed

MOT #2	2007-09-11 08:05
MOT test number	991574757206
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2007-07-24 10:38
MOT test number	572925807267
Result	✓ Passed
Notice	Both front tyres wearing on outer edges



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
15 March 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-08-20
Last registration	2024-03-01
Complete history	See info



Registration #1	2004-08-20	17 mi
Registration #2	2007-07-24	18.964 mi
Registration #3	2007-09-11	19.642 mi
Registration #4	2008-08-20	27.252 mi
Registration #5	2009-08-26	33.052 mi
Registration #6	2010-08-24	36.227 mi
Registration #7	2011-07-01	38.128 mi
Registration #8	2012-06-12	40.959 mi
Registration #9	2013-06-12	46.068 mi
Registration #10	2014-06-23	49.412 mi
Registration #11	2015-06-01	52.868 mi
Registration #12	2016-06-27	56.932 mi
Registration #13	2016-06-27	56.932 mi
Registration #14	2016-06-27	56.932 mi
Registration #15	2016-06-27	56.932 mi
Registration #16	2016-06-27	56.932 mi
Registration #17	2016-06-27	56.932 mi
Registration #18	2016-06-27	56.932 mi
Registration #19	2016-06-27	56.932 mi
Registration #20	2016-06-27	56.932 mi
Registration #21	2016-06-27	56.932 mi
Registration #22	2016-06-27	56.932 mi
Registration #23	2016-06-27	56.932 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1245 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	LT181032820