





report date: 2024-03-28

General information

| Make | TOYOTA |
|---------------------|---------------------------|
| Model | HILUX INVINCIBLE D-4D DCP |
| Colour | Black |
| Year of manufacture | 2009 |
| Top speed | 109 mph |
| 0 - 60 mph | 10.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 194 BHP |
|-------------------------|---------------------|
| Max. torque | 430 Nm at 1.400 rpm |
| Engine capacity | 2.982 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.8 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 40.9 mpg |



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

Date 2021-10-24

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-10-23 |
|------|------------|
| | |

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date | 2025-01-04 |
|--------------------|------------|
| MOT pass rate | 81 % |
| MOT passed | 13 |
| Failed MOT tests | 3 |
| Total advice items | 14 |
| Total items failed | 6 |

| MOT #16 | 2023-12-22 09:30 |
|------------------|------------------|
| MOT test number | 452496756518 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-04 |

| MOT #15 | 2022-12-21 08:53 |
|-----------------|------------------|
| MOT test number | 807885507486 |
| Result | ✓ Passed |

| MOT #14 | 2022-01-05 10:55 |
|-----------------|------------------|
| MOT test number | 137842610248 |
| Result | ✓ Passed |

| MOT #13 | 2021-07-28 15:17 |
|---------|------------------|

MOT test number 707273423733

Result

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake pipe corroded, covered in grease or other material front to rear brake pipe into compensator. (1.1.11 (c))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2020-08-10 15:22 **MOT** test number 528492373270 ✓ Passed Result Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i)) **Advice** Offside Rear Leaf spring has slight wear in a shackle pin and/or bush (5.3.4 (a) (i)) **Advice** Play in steering rack inner joint(s) Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i)) **Advice** Nearside Rear Leaf spring has slight wear in a shackle pin and/or bush (5.3.4 (a) (i))

MOT #11 2019-05-09 07:32
MOT test number 836189415030
Result ✓ Passed

MOT test number

Result

Nearside Front Position lamp not working (4.2.1 (a))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9

MOT test number

411497917564

Result

Advice Offside Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)

Advice Nearside Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)

CarCheck.co.uk page 4/13



MOT #8

YTO9HHY
report date: 2024-03-28

2018-05-09 10:27

MOT test number 363648053093

Result X Failed

Advice Nearside Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Offside Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)

MOT #7 2017-05-02 08:03

MOT test number 728154788318

Result ✓ Passed

Advice Brake pipe slightly corroded Front to back brake pipes and front caliper link pipes. (3.6.B.2c)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2016-05-03 11:15

MOT test number 621670611701

MOT #5 2015-04-13 15:48

MOT test number 518393805121

Result

Passed

MOT #4 2014-04-11 11:13

MOT test number 756511804164

Result
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

| MOT #3 | 2014-04-11 11:13 |
|---|---|
| MOT test number | 426811304102 |
| Result | ★ Failed |
| Pass with rectification | Nearside Front Wheel stud(s) missing (4.2.A.1e) |
| Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) | |

| MOT #2 | 2013-09-18 15:38 |
|-----------------|------------------|
| MOT test number | 975791563280 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2012-05-21 11:03 |
| MOT test number | 845812542184 |
| Result | ✓ Passed |

CarCheck.co.uk page 6/13



4 January 2025

Tax & MOT check

MOT expiry date



Full MOT history See MOT history

CarCheck.co.uk page 7/13




report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

| Owner history | |
|---|-------------|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full | |
| ******** | |
| *************************************** | |
| *********** | |
| ********* | |
| *************************************** | |
| ************ | |
| Plate changes | More info > |
| See in this check if this TOYOTA had different number plates. | |
| Number of plates | |
| Current registration | NK NK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info |

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info >

CarCheck.co.uk page 11/13



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2009-03-20 |
| Last registration | 2023-12-22 |
| Complete history | See info |



| Registration #1 | 2009-03-20 | 23 mi |
|------------------|------------|-----------|
| Registration #2 | 2012-05-21 | 22.325 mi |
| Registration #3 | 2013-09-18 | 31.971 mi |
| Registration #4 | 2014-04-11 | 33.703 mi |
| Registration #5 | 2015-04-13 | 51.562 mi |
| Registration #6 | 2016-05-03 | 67.075 mi |
| Registration #7 | 2017-05-02 | 80.524 mi |
| Registration #8 | 2018-05-09 | 97.093 mi |
| Registration #9 | 2018-05-09 | 97.093 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.177 es |

More info >

page 12/13 CarCheck.co.uk



Car features

| S0225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Dimensions & weight

| Width | 1835 mm |
|---------------------|---------|
| Height | 1810 mm |
| Length | 5255 mm |
| Kerb weight | 1885 kg |
| Max. allowed weight | 2940 kg |

Additional information

| Fuel delivery | Direct Injection |
|-----------------|------------------|
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 1KD7547097 |

CarCheck.co.uk page 13/13