





report date: 2024-03-29

## General information

Make	NISSAN
Model	PIXO VISIA
Colour	Black
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg



CarCheck.co.uk page 1/11



# Internet history

#### Entry 1

Date	2021-08-08	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT #14 2022-07-11 09:58

MOT test number 749051352309

Result \( \sqrt{Passed} \)

Next expiry date 2023-07-16

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2022-07-11 09:58

MOT test number 323485695678

**Result** X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #12** 2021-07-17 09:33

**MOT test number** 962234704324

**Advice** Front slight cracking on n/s o/s tyre treads.

**MOT #11** 2020-09-11 10:41

**MOT test number** 768570972616

Result \( \sqrt{Passed} \)

**MOT #10** 2019-09-19 10:09

**MOT test number** 410315969240

Result \( \sqrt{Passed} \)

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**Advice** Undertrays fitted obscuring components

CarCheck.co.uk page 3/11



**MOT #9** 2019-09-13 15:15

**MOT test number** 352030134247

**Result** X Failed

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Undertrays fitted obscuring components

**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MAJOR Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #8 2018-09-19 08:41

**MOT test number** 686383622020

Result \square Passed

MOT #7 2018-09-19 08:41

**MOT test number** 852744934040

**Result** X Failed

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

MOT #6 2017-09-18 15:17

**MOT test number** 436009848264

**Result** ✓ Passed

MOT #5 2017-09-18 12:39

**MOT test number** 416471048302

**Result** X Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 4/11



MOT #4 2016-09-13 08:45
MOT test number 692565252813

MOT #3 2015-09-14 13:03

**MOT test number** 775466857630

**Result** ✓ Passed

MOT #2 2015-09-04 15:37

**MOT test number** 990486155986

Result X Failed

**Fail** Offside Front wheel bearing rough when rotated (2.5.A.2)

MOT #1 2014-08-20 09:14

**MOT test number** 746002034293

**Notice** Off side rear tyre perishing

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



**HJ61WFY** 

report date: 2024-03-29

Owner	history
O WILCI	,

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN		
have? Check it in the premium report and see all owner registrations. Download the full r	eport <u>here</u> .	
***************************************		
************		
MANAGEMENT CONTRACTOR		
***************************************		
	More info >	
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		
Current registration	UK ZIS	
Plate since		
Current registration	NE NE	
Plate since		
	More info >	

page 8/11 CarCheck.co.uk



### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-16
Last registration	2022-07-11
Complete history	See info



Registration #1	2011-09-16	8 mi
Registration #2	2014-08-20	21.715 mi
Registration #3	2015-09-04	36.172 mi
Registration #4	2015-09-14	36.172 mi
Registration #5	2016-09-13	49.637 mi
Registration #6	2017-09-18	59.226 mi
Registration #7	2017-09-18	59.226 mi
Registration #8	2018-09-19	65.705 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		0.00 44
Registration #15		11.777 ms

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

D: 100	ensior	- C		ьь
	Ansini	15 ~	$\mathbf{w}$	

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	133813

CarCheck.co.uk page 11/11