



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE RENAULTSPORT
Colour	Grey
Year of manufacture	2010
Top speed	155 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	247 BHP
Max. torque	340 Nm at 3.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	195 g/km
CO2 label	J





Internet history

Entry 2


Date	2023-06-05
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-01
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-28
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	33
Total items failed	3

MOT #14	2023-10-18 08:54
MOT test number	866092024854
Result	✓ Passed
Next expiry date	2024-10-28
Advice	Front Track rod end ball joint has slight play o/s & n/s rack ends (2.1.3 (b) (i))

MOT #13	2022-10-29 08:17
MOT test number	769585025681
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Upper Suspension component ball joint has slight play (5.3.4 (a) (i))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #12	2021-10-25 11:37
MOT test number	375770030356
Result	✓ Passed

**MOT #11**

2021-10-22 12:49

MOT test number

499553073241

Result

✗ Failed

Fail Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #10**

2021-09-17 11:04

MOT test number

370688442073

Result

✓ Passed

Advice Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #9**

2020-09-19 14:15

MOT test number

224546196179

Result

✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8**

2019-09-16 16:17

MOT test number

224163813231

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2018-09-22 14:26**MOT test number** 426192497840**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #6** 2017-09-16 08:04**MOT test number** 683581595547**Result** ✓ Passed**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside rear brake is sticking**MOT #5** 2017-09-15 13:44**MOT test number** 234369453005**Result** ✗ Failed**Advice** Offside rear brake is sticking**Fail** Front brake application uneven (3.7.B.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**MOT #4** 2016-09-19 08:27**MOT test number** 546120156781**Result** ✓ Passed**Advice** Engine covers and under trays fitted at time of test.

**MOT #3** 2015-09-21 10:39**MOT test number** 784005695592**Result** ✓ Passed

- Advice** Under trays fitted
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Engine covers fitted
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2014-09-17 09:40**MOT test number** 115470864277**Result** ✓ Passed

- Notice** Nail in nearside rear tyre
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #1 2013-09-17 12:47**MOT test number** 445380863298**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
28 October 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	28 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-21
Last registration	2023-10-18
Complete history	See info



Registration #1	2010-09-21	19 mi
Registration #2	2013-09-17	27.262 mi
Registration #3	2014-09-17	34.625 mi
Registration #4	2015-09-21	36.980 mi
Registration #5	2016-09-19	39.241 mi
Registration #6	2017-09-15	40.311 mi
Registration #7	2017-09-16	40.311 mi
Registration #8	2018-09-22	41.357 mi
Registration #9	2019-09-16	42.459 mi
Registration #10	2020-09-22	43.561 mi
Registration #11	2021-09-22	44.663 mi
Registration #12	2022-09-22	45.765 mi
Registration #13	2023-09-22	46.867 mi
Registration #14	2024-09-22	47.969 mi
Registration #15	2025-09-22	49.071 mi
Registration #16	2026-09-22	50.173 mi
Registration #17	2027-09-22	51.275 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1848 mm
Height	1435 mm
Length	4299 mm
Wheel base	2636 mm
Kerb weight	1350 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	C002513