



SPI2LDF

report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER TD HARD TOP
Colour	Green
Year of manufacture	2012
Top speed	90 mph
0 - 60 mph	15.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	29.1 mpg
Consumption combined	25.5 mpg







Internet history

Entry 2

Date	2021-07-10
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-09
Pictures	26
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-11
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	18
Total items failed	9

MOT #12	2023-08-10 12:40
MOT test number	699114696483
Result	✓ Passed
Next expiry date	2024-08-11

MOT #11	2023-08-07 12:49
MOT test number	239401429163
Result	✗ Failed
Fail	Offside Rear Brake pipe excessively corroded axle (1.1.11 (c))
Advice	Offside Rear hub seal leaking
Fail	Offside Headlamp aim too low and too far to the right. (4.1.2 (a))
Fail	Offside Rear Brake pad(s) contaminated with oil (1.1.13 (b))
Fail	Nearside Headlamp aim too low (4.1.2 (a))

MOT #10	2022-08-12 10:15
MOT test number	931227559265
Result	✓ Passed
Advice	Items removed from driver's view prior to test
Advice	Rear Prop shaft joint worn, but not excessively (6.1.7 (c) (i))
Advice	Steering linkage ball joint has slight play Steering box drop arm ball joint (2.1.3 (b) (i))



MOT #9	2021-08-12 13:28
MOT test number	493450204870
Result	✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8	2020-09-16 13:03
MOT test number	500837174980
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Driver's door hinge deteriorated but the door can still be readily opened and closed both hinges (6.2.3 (c) (i))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Rear Prop shaft joint worn, but not excessively (6.1.7 (c) (i))
Advice	Lower Front passenger door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))
Minor	Windscreen wiper blade defective both front blades (3.4 (b) (i))

MOT #7	2019-07-09 09:35
MOT test number	652068981447
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #6	2018-07-12 08:22
MOT test number	750624849560
Result	✓ Passed

MOT #5	2017-07-11 08:22
MOT test number	123660849117
Result	✓ Passed
Advice	Nearside Front Ball joint has slight play (2.2.B.1f)

**MOT #4** 2016-07-13 07:58**MOT test number** 318169621630**Result** ✓ Passed**MOT #3** 2016-07-04 08:45**MOT test number** 495160105030**Result** ✗ Failed

- Fail** Nearside Headlamp not working on main beam (1.7.5a)
- Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Fail** Nearside Rear Radius arm has excessive play in a pin/bush front (2.4.G.2)
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Fail** Offside Rear Radius arm has excessive play in a pin/bush front (2.4.G.2)

MOT #2 2016-02-01 15:03**MOT test number** 139210148320**Result** ✓ Passed

- Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement drop link (2.4.G.2)
- Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

MOT #1 2015-02-27 12:17**MOT test number** 767168255069**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
11 August 2024

Tax status	Valid until 1 August
-------------------	----------------------

Days left	93
------------------	----

MOT expiry date	11 August 2024
------------------------	----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	SP12LDF
Plate since	2024-03-29
Current registration	SP12LDF
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-22
Last registration	2023-08-10
Complete history	See info



Registration #1	2012-03-22	27 mi
Registration #2	2015-02-27	50.408 mi
Registration #3	2016-02-01	52.290 mi
Registration #4	2016-07-04	66.527 mi
Registration #5	2016-07-13	66.528 mi
Registration #6	2017-07-11	80.267 mi
Registration #7	2018-07-12	98.505 mi
Registration #8	2019-07-09	116.510 mi
Registration #9	2020-06-29	135.277 mi
Registration #10	2021-06-29	154.044 mi
Registration #11	2022-06-29	172.811 mi
Registration #12	2023-06-29	191.578 mi
Registration #13	2024-06-29	210.345 mi
Registration #14	2025-06-29	229.112 mi
Registration #15	2026-06-29	247.879 mi

More info >



Dimensions & weight

Width	1790 mm
Height	2181 mm
Length	4625 mm
Kerb weight	1953 kg
Max. allowed weight	3050 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	120225031533DT224