





General information

Make	VOLVO
Model	V50 D2 R-DESIGN
Colour	Silver
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С







Internet history

Entry 2	
Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 1	
Date	2021-01-22
Pictures	11
Listing price	<u>View report</u>



source: yesauto.com









MOT history

MOT expiry date	2025-04-08
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #11	2024-04-04 10:17
MOT test number	688789471343
Result	✓ Passed
Next expiry date	2025-04-08

MOT #10	2023-04-04 09:05
MOT test number	793195058034
Result	✓ Passed

МОТ #9	2022-04-04 12:03
MOT test number	668140117545
Result	✓ Passed

MOT #8	2022-04-04 08:03
MOT test number	524724026165
Result	🗙 Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn badly on i	nner edge (5.2.3 (e))

MOT #7	2021-04-09 09:03
MOT test number	276867084389
Result	✓ Passed





2017 10 20 00 10

MOT #6	2019-11-11 09:24
MOT test number	459693159465
Result	✓ Passed
MOT #5	2018-11-15 10:03
MOT test number	641764401999
Result	✓ Passed

MOT #4		2017-10-28 08:19
MOT test	number	727370880079
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Nail in tyre	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3		2016-11-14 10:25
MOT test	number	850257494084
Result		✓ Passed
Advice	Oil leak	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	

MOT #2	2015-10-30 09:58
MOT test number	372057916523
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #1		2014-11-11 10:11
MOT test	number	986465714314
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	



Tax & MOT check

Tax due: 1 October 2024	✓ Taxed	Expires: 8 April 2025	✓ МОТ
Tax status			Valid until 1 October
Days left			156
MOT expiry date			8 April 2025
Full MOT history			See MOT history
Tax calculation			
Vohiclo class		10	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Correct registration	
Plate since	
	More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-11-21
Last registration	2024-04-04
Complete history	<u>See info</u>



Registration #1	2011-11-21	29 mi
Registration #2	2014-11-11	31.911 mi
Registration #3	2015-10-30	40.495 mi
Registration #4	2016-11-14	48.882 mi
Registration #5	2017-10-28	56.459 mi
Registration #6	2018-11-15	65.304 mi
Registration #7	2019-11-11	72.468 mi
Registration #8		11.777 esi
Registration #9		11.177 esi
Registration #10		11.777 esi
Registration #11		11.177 esi
Registration #12		11.117 esi
Registration #13		11.117 esi
Registration #14		11.777 esi





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg
Additional information	
Fuel tank capacity	52
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	1708102