





report date: 2024-03-29

# General information

| Make                | PEUGEOT               |
|---------------------|-----------------------|
| Model               | PARTNER BLUE HDI S L1 |
| Colour              | White                 |
| Year of manufacture | 2016                  |
| Top speed           | 101 mph               |
| Gearbox             | 5 speed Manual        |

# Engine & fuel consumption

| Power                   | 100 BHP             |
|-------------------------|---------------------|
| Max. torque             | 254 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 55.4 mpg            |
| Consumption extra urban | 74.3 mpg            |
| Consumption combined    | 65.7 mpg            |
| CO2 emission            | 112 g/km            |
| CO2 label               | С                   |



CarCheck.co.uk page 1/11



report date: 2024-03-29

# Internet history

# Entry 1

Date 2021-07-03

Pictures 2

Listing price <u>View report</u>





source: cargurus.co.uk

CarCheck.co.uk page 2/11



NV66KZG report date: 2024-03-29

MOT history

| MOT expiry date    | 2024-07-15 |
|--------------------|------------|
| MOT pass rate      | 83 %       |
| MOT passed         | 5          |
| Failed MOT tests   | 1          |
| Total advice items | 8          |
| Total items failed | 3          |

| MOT #6    |   | 2023-07-12 14:32 |
|-----------|---|------------------|
| MOT test  | number  | 798613836955     |
| Result    |   | ✓ Passed         |
| Next expi | ry date   | 2024-07-15       |
| Advice    | Offside Front Drive shaft joint worn, but not excessively (6.1.7 (c) (i))       |                  |
| Advice    | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))            |                  |
| Advice    | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) | (ii))            |
| Advice    | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))          |                  |

| MOT #5                         | 2023-07-12 14:32   |
|--------------------------------|--|
| MOT test number                | 832100209849   |
| Result                         | <b>▼</b> Failed  |
| Pass with rectification        | Nearside Front Position lamp not working (4.2.1 (a) (ii))              |
| Pass with rectification        | Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| <b>Advice</b> Nearside Front T | yre worn close to legal limit/worn on edge (5.2.3 (e))                 |
| Pass with rectification        | Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))     |
| Advice Front Brake disc        | worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))   |
| Advice Offside Front Dri       | ve shaft joint worn, but not excessively (6.1.7 (c) (i))               |
| Advice Offside Rear Tyre       | e worn close to legal limit/worn on edge (5.2.3 (e))                   |

CarCheck.co.uk page 3/11



report date: 2024-03-29

| MOT #4          | 2022-07-16 07:51 |
|-----------------|------------------|
| MOT test number | 383084591061     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #3          | 2021-07-02 15:29 |
| MOT test number | 988125464243     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #2          | 2020-11-17 13:01 |
| MOT test number | 991615333147     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #1          | 2019-11-13 15:45 |
| MOT test number | 938966346217     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 4/11



report date: 2024-03-29

# Tax & MOT check



| Tax status       | Valid until 1 February |
|------------------|------------------------|
| Days left        | 278                    |
| MOT expiry date  | 15 July 2024           |
| Full MOT history | See MOT history        |

# Tax calculation

| Vehicle class             | 39         |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months)  | £ 151,25,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

# Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

# Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



furthe scinors

**NV66KZG** 

report date: 2024-03-29

# For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

# Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 8          |
| First mileage registration | 2016-12-30 |
| Last registration          | 2023-07-12 |
| Complete history           | See info   |



| Registration #1 | 2016-12-30 | 19 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2019-11-13 | 27.446 mi |
| Registration #3 | 2020-11-17 | 34.456 mi |
| Registration #4 | 2021-07-02 | 41.114 mi |
| Registration #5 |            | 91.777 es |
| Registration #6 |            | D.777 es  |
| Registration #7 |            | 11.777 es |
| Registration #8 |            | 11.777 es |

More info >

page 10/11 CarCheck.co.uk



NV66KZG report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| 50501 |                  |
| S0566 |                  |
| S0567 |                  |
| 50569 |                  |

# Dimensions & weight

| Width               | 1810 mm |
|---------------------|---------|
| Height              | 1828 mm |
| Length              | 4380 mm |
| Wheel base          | 2728 mm |
| Kerb weight         | 1314 kg |
| Max. allowed weight | 2170 kg |

# Additional information

| Fuel delivery   | Direct Injection |
|-----------------|------------------|
| Number of seats | 2                |
| Number of axles | 2                |
| Engine number   | JBHB0013409      |

CarCheck.co.uk page 11/11