



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI ALTITUDE
Colour	Blue
Year of manufacture	2007
Top speed	125 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.9 mpg
Consumption extra urban	33.6 mpg
Consumption combined	26.9 mpg
CO2 emission	278 g/km
CO2 label	M





MOT history

MOT expiry date	2021-01-17
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	21
Total items failed	6

**MOT #14**

2021-03-18 09:08

MOT test number

754011219552

Result**✗ Failed**

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge centre (5.2.3 (e))
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))
- Advice** Central Prop shaft bearing has slight play (6.1.7 (b) (i))
- Advice** Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Sub-frame pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement offside and nearside (5.3.4 (a) (i))

MOT #13

2020-01-16 15:18

MOT test number

843765469413

Result**✓ Passed**

- Advice** Offside Front o/s/f brake binding slightly
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**MOT #12** 2019-01-17 14:14**MOT test number** 387786724596**Result** ✓ Passed**MOT #11** 2019-01-17 11:37**MOT test number** 239939904389**Result** ✗ Failed

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps Both rear (4.7.1 (b) (ii))

MOT #10 2018-01-16 11:26**MOT test number** 428678323667**Result** ✓ Passed

Advice Front Inner Tyre worn close to the legal limit Both (4.1.E.1)

MOT #9 2016-12-20 16:19**MOT test number** 816974794890**Result** ✓ Passed**MOT #8** 2016-01-18 15:25**MOT test number** 929550663513**Result** ✓ Passed**MOT #7** 2015-01-05 09:53**MOT test number** 825345105036**Result** ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

**MOT #6** 2014-01-08 13:57**MOT test number** 895328104062**Result** ✓ Passed**MOT #5** 2014-01-08 10:13**MOT test number** 378578404019**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2013-01-07 11:59**MOT test number** 348607703028**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**MOT #3** 2012-01-09 11:27**MOT test number** 209769502093**Result** ✓ Passed**Notice** Parking brake pedal travel**MOT #2** 2011-04-21 13:24**MOT test number** 216311011497**Result** ✓ Passed**MOT #1** 2010-04-26 13:41**MOT test number** 813516710163**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	BK07SYZ
Plate since	2024-03-29
Current registration	BK07SYZ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-04-26
Last registration	2021-03-18
Complete history	See info



Registration #1	2007-04-26	26 mi
Registration #2	2010-04-26	50.936 mi
Registration #3	2011-04-21	71.600 mi
Registration #4	2012-01-09	76.315 mi
Registration #5	2013-01-07	89.928 mi
Registration #6	2014-01-08	98.847 mi
Registration #7	2014-01-08	98.847 mi
Registration #8	2015-01-05	107.916 mi
Registration #9	2016-01-05	117.985 mi
Registration #10	2017-01-05	128.054 mi
Registration #11	2018-01-05	138.123 mi
Registration #12	2019-01-05	148.192 mi
Registration #13	2020-01-05	158.261 mi
Registration #14	2021-01-05	168.330 mi
Registration #15	2022-01-05	178.399 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2530 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKS 056903