





report date: 2024-03-29

General information

Make	ТОУОТА
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Blue
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	130 Nm at 4.400 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2021-03-05
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	25
Total items failed	13

MOT #18	2020-03-03 15:33
MOT test number	610661550987
Result	✓ Passed
Next expiry date	2021-03-05
Advice Front tyres close to 1.6mm	

MOT #17	2020-03-03 11:24
MOT test number	519386081586
Result	× Failed
Advice Front Service brake binding but not excessively (1.2.1 (f)) Fail Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))	

MOT #16		2019-02-19 15:00
MOT test	number	369471163644
Result		✓ Passed
Advice Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (in Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (in Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (in Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (in Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (in Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (in Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (in Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (in Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (in Rear Brake disc worn))	

CarCheck.co.uk page 2/13



Pass with rectification

Result

FD54LDJ report date: 2024-03-29

X Failed

MOT #15 2018-03-03 17:16

MOT test number 659162701421

Result ✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #14 2018-03-03 17:16

MOT test number 662802355704

Central Rear Stop lamp not working (1.2.1b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Offside Front Headlamp aim too low (1.8)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Nearside Front Headlamp aim too low (1.8)

MOT #13 2017-03-04 15:58

MOT test number 560444623073

Advice Nearside Headlamp damaged but light output not reduced (1.7.5a)

Advice Brake disc worn, pitted or scored, but not seriously weakened front & rear (3.5.1i)

Advice Parking brake lever has little reserve travel (3.1.6b)

CarCheck.co.uk page 3/13



MOT #12 2017-03-04 15:58

MOT test number 477798743406

Result X Failed

Advice Nearside Headlamp damaged but light output not reduced (1.7.5a)

Pass with rectification Bonnet cannot be secured in the closed position (8.4.1)

Advice Brake disc worn, pitted or scored, but not seriously weakened front & rear (3.5.1i)

Advice Parking brake lever has little reserve travel (3.1.6b)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #11 2016-03-05 13:18

MOT test number 308120834827

Result ✓ Passed

MOT #10 2015-02-27 14:30

MOT test number 426518755047

Result ✓ Passed

MOT #9 2014-03-06 14:03

MOT test number 865785864034

Notice Front suspension subframe corroded

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Rear antiroll bar corroded

CarCheck.co.uk page 4/13



MOT #8 2014-03-03 14:14

MOT test number 205912764008

Result X Failed

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Notice Rear antiroll bar corroded

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Suspension arm synthetic bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Notice Front suspension subframe corroded

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #7	2013-02-26 11:08
MOT test number	489077453063

Result

Passed

MOT #6 2012-02-16 16:00
MOT test number 406397342004

Result

Passed

MOT #5 2011-02-25 15:45

MOT test number 955506751041

Result \(\sqrt{Passed} \)

MOT #4 2010-02-27 14:26

MOT test number 121488950497

CarCheck.co.uk page 5/13



Passed

MOT #3 2010-02-27 11:22

MOT test number 164498650465

Result × Failed

Fail Front registration plate character(s) likely to be misread (6.3.4b)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2009-02-28 13:27

MOT test number 910669259087

Result \sqrt{Passed}

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2007-12-29 10:09

MOT test number 154293767392

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13





Tax & MOT check



Х мот

Tax expired: 12 January 2021 Expired: 5 March 2021

Tax status	Expired at 12 January 2021
Days left	1203 days too late
MOT expiry date	5 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-11-29
Last registration	2020-03-03
Complete history	See info



Registration #1	2004-11-29	22 mi
Registration #2	2007-12-29	20.374 mi
Registration #3	2009-02-28	36.111 mi
Registration #4	2010-02-27	44.717 mi
Registration #5	2010-02-27	44.717 mi
Registration #6	2011-02-25	50.466 mi
Registration #7	2012-02-16	53.264 mi
Registration #8	2013-02-26	60.175 mi
Registration #9	2014-03-03	63.248 mi
Registration #10	2014-03-06	63.270 mi
Registration #10 Registration #11	2014-03-06	63.270 mi
	2014-03-06	63.270 mi
Registration #11	2014-03-06	63.270 mi
Registration #11 Registration #12	2014-03-06	63.270 mi
Registration #11 Registration #12 Registration #13	2014-03-06	63.270 mi
Registration #11 Registration #12 Registration #13 Registration #14	2014-03-06	63.270 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2014-03-06	63.270 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2014-03-06	63.270 mi

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1130 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	4ZZU499329

CarCheck.co.uk page 13/13