





General information

Make	NISSAN
Model	NV200 E ACENTA
Colour	White
Year of manufacture	2015
Top speed	76 mph
0 - 60 mph	14.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm
Fuel type	Electricity





Internet history

Entry 1

Date Pictures 2022-06-24

40

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-07
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	7
Total items failed	13

MOT #11	2023-07-08 11:23
MOT test number	182654317070
Result	✓ Passed
Next expiry date	2024-07-07

MOT #10	2023-07-05 07:22
MOT test number	145166369890
Result	🗙 Failed
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach (5.2.3 (d) (i))	n the ply or cords
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	

МОТ #9	2022-07-04 12:05
MOT test number	482119591518
Result	✓ Passed
МОТ #8	2022-06-24 15:26
MOT test number	836166223708
Result	🗙 Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Offside Parking brake inoperative on one side (1.4.1 (a))

Fail





MOT #7		2021-02-19 16:30
MOT test n	umbor	
	umber	651280822101
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
MOT #6		2021-02-19 12:54
MOT test n	umber	143713138526
Result		🗙 Failed
	side Front Drive shaft joint constant velocity boot split or insecure, no longer proken (6.1.7 (g) (ii))	prevents the ingress
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
MOT #5		2020-03-06 16:47
MOT test n	umber	494054284334
Result		✓ Passed
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
MOT #4		2020-03-02 12:07

MOT #4	2020-03-02 12:07
MOT test number	271587785664
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge very close to lim	it (5.2.3 (e))
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Fail Nearside Parking brake inoperative on one side (1.4.1 (a))	
Fail Windscreen washer provides insufficient washer liquid cant check wipers (3.5 (a))
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	






MOT #3	2019-03-18 12:52
MOT test number	975076794851
Result	✓ Passed
MOT #2	2019-03-11 09:56
MOT test number	758372278074
Result	🗙 Failed
Fail Offside Parking brake inoperative on one side (1.4.1 (a))	
Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its str	ructure (5.2.3 (d) (ii))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
FailOffside Rear Leaf spring fractured (5.3.1 (b) (i))	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MOT #1	2018-03-16 16:17

MOT #1	2018-03-16 16:17
MOT test number	123871063889
Result	✓ Passed



Tax & MOT check







Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

annesses.	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-12
Last registration	2023-07-08
Complete history	<u>See info</u>



Registration #1	2015-03-12	7 mi
Registration #2	2018-03-16	33.386 mi
Registration #3	2019-03-11	44.551 mi
Registration #4	2019-03-18	44.551 mi
Registration #5	2020-03-02	54.987 mi
Registration #6	2020-03-06	54.989 mi
Registration #7	2021-02-19	57.408 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.117 esi





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	75%
Children	80%
Pedestrian	60%
Safety systems	38%
Overall rating	65%
Video	see crash video



Additional information	
Fuel delivery	Not Applicable
Number of doors	5
Number of seats	2
Engine number	082233A