

Ford



General information

Make	FORD
Model	B-MAX ZETEC
Colour	Blue
Year of manufacture	2014
Top speed	109 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 99 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С







Internet history

Entry	1

Date Pictures 2021-09-04

12

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-30
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	17
Total items failed	4

MOT #11		2023-09-09 08:16
MOT test	number	423945966707
Result		✓ Passed
Next expiry date 2024-09-		2024-09-30
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #10	2022-09-30 10:39	
MOT test number	609559027955	
Result	✓ Passed	
Advice Front exhaust deteriorated		
Advice Front Tyre worn close to legal limit/worn on edge n/s o/s (5.2.3 (e))		
Minor Nearside Rear Inner Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	4 (a) (ii))	
Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

МОТ #9	2021-10-01 07:55
MOT test number	685642087879
Result	✓ Passed





MOT #8		2021-09-30 15:21
MOT test	number	874219125009
Result		🗙 Failed
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MOT #7		2020-11-06 15:57
MOT test	number	149750403256
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))

МОТ #6	2020-11-06 15:57
MOT test number	171156651960
Result	× Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice Nearside Front II (a) (ii))	nner Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14
Pass with rectification (h))	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2019-11-09 12:21
MOT test number	952988640139
Result	✓ Passed
MOT #4	2018-10-31 14:26
MOT test number	386920470126
Result	✓ Passed





MOT #3		2018-02-08 14:50
MOT test numbe	er in the second s	243394502099
Result		✓ Passed
MOT #2		2017-01-31 17:09
MOT test numbe	er	964235541092
Result		✓ Passed
Advice Nears	side Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Offsid	le Rear Child Seat fitted not allowing full inspection of adult belt	
MOT #1		2017-01-31 13:45
MOT test numbe	er	202203891564
Result		🗙 Failed
Advice Offsid	le Rear Child Seat fitted not allowing full inspection of adult belt	

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

FailNearside Front Inner Tyre has a lump, caused by separation or partial failure of its structure(4.1.D.1b)



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 30 September 2024
Tax status	Valid until 1 October
Days left	156
MOT expiry date	30 September 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		ARMP
Туре		
Damage 2		AMPLE
	E E	AT I
Date		*
Category	AMA	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-02-28
Last registration	2023-09-09
Complete history	See info



Registration #1	2014-02-28	7 mi
Registration #2	2017-01-31	15.295 mi
Registration #3	2017-01-31	15.295 mi
Registration #4	2018-02-08	22.465 mi
Registration #5	2018-10-31	26.095 mi
Registration #6	2019-11-09	38.166 mi
Registration #7	2020-11-06	47.236 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		

More info >





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	ES23713