





General information

Make	HONDA
Model	HR-V I-DTEC SE NAVI
Colour	Red
Year of manufacture	2016
Top speed	119 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	В








Internet history

Entry 2	
Date	2021-08-23
Pictures	10
Listing price	View report







source: autoonline.co.uk

Entry 1

Date

Pictures

Listing price

2021-08-21

40

View report



source: heycar.co.uk









MOT history

MOT expiry date	2024-08-14
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	15
Total items failed	0

МОТ #6	2023-08-11 15:06
MOT test number	312289692396
Result	🗸 Passed
Next expiry date	2024-08-14
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge 215/55r17 (5.2.3 (e))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	



CU16EYM report date: 2024-03-29

MOT #5		2023-08-11 10:51
MOT test	number	422605373468
Result		🗙 Failed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 215/55r17 (5.2.3 (e))	
MAJOR	Electronic parking brake warning indicates a malfunction (1.1.6 (e))	
DANGE	ROUS Front Tyre has ply or cords exposed both (215/55r17 (5.2.3 (d) (ii))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

MOT #4	2022-07-28 14:52
MOT test number	126514384130
Result	✓ Passed

MOT #3	2021-07-26 14	:00
MOT test	number 629283265	106
Result	V Pas	sed
Minor (i))	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a)

MOT #2	2020-08-03 09:29
MOT test number	931233814378
Result	✓ Passed





MOT #1	2019-08-03 10:57
MOT test number	843469801418
Result	✓ Passed
Advice Front Suspension arm pin or bush worn but not resulting in exce arm rear pin bush (5.3.4 (a) (i))	essive movement N/S/F O/S/F lower



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 14 August 2024	✓ мот
Tax status			Valid until 1 August
Days left			93
MOT expiry date			14 August 2024
Full MOT history			See MOT history
Tax calculation			
		40	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this HONDA had different number plat	es.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-08-15
Last registration	2023-08-11
Complete history	See info



Registration #1	2016-08-15	23 mi
Registration #2	2019-08-03	23.438 mi
Registration #3	2020-08-03	37.839 mi
Registration #4	2021-07-26	51.837 mi
Registration #5		11.117 esi
Registration #6		11.117 esi
Registration #7		11.777 esi
Registration #8		11.117 esi
Registration #9		11.777 esi

More info >





Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	72%
Safety systems	71%
Overall rating	79%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1772 mm
Height	1605 mm
Length	4294 mm
Wheel base	2610 mm
Kerb weight	1404 kg
Max. allowed weight	1870 kg
Additional information	
Additional information Fuel tank capacity	50 I
	50 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5