



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Silver
Year of manufacture	2005
Top speed	116 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	155 Nm at 4.150 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-09-06
Pictures	15
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-09-04
Pictures	15
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-03
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	41
Total items failed	13

MOT #20	2024-01-04 11:54
MOT test number	881434551159
Result	✓ Passed
Next expiry date	2025-01-03

MOT #19	2023-01-04 12:27
MOT test number	213222053761
Result	✓ Passed
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #18	2022-01-04 16:19
MOT test number	963954312080
Result	✓ Passed



MOT #17

2020-11-26 16:07

MOT test number

753726559001

Result

✓ Passed

- Advice

Central Exhaust shield loose
- Minor

Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice

Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Minor

Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16**

2020-11-26 14:32

**MOT test number**

991233998494

**Result****✗ Failed**

- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Rear Passenger's seat insecure (6.2.6 (a) (ii))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Central Exhaust shield loose
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Nearside Rear Passenger's seat insecure (6.2.6 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15**

2019-11-25 09:12

**MOT test number**

363055984832

**Result****✓ Passed**

- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive transmisson (8.4.1 (a) (i))
- Advice** Central heat shield loose

**MOT #14** 2018-11-12 12:20**MOT test number** 801980514712**Result** ✓ Passed

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Both rear tyres cracking between treads
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**MOT #13** 2018-11-09 10:40**MOT test number** 850719149842**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Both rear tyres cracking between treads

**MOT #12** 2017-11-14 11:24**MOT test number** 916883456655**Result** ✓ Passed

- Advice** Rear shocks slightly weak
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

**MOT #11** 2016-11-08 12:48**MOT test number** 163893130389**Result** ✓ Passed**MOT #10** 2016-11-08 11:28**MOT test number** 471666788357**Result** ✗ Failed

- Fail** Nearside Front Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)
- Fail** Offside Front Direction indicator not working (1.4.A.2c)
- Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)

**MOT #9** 2015-11-03 09:59**MOT test number** 893954273262**Result** ✓ Passed

- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

**MOT #8** 2015-11-02 10:41**MOT test number** 115843820727**Result** ✗ Failed**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #7** 2014-11-03 12:05**MOT test number** 379757704322**Result** ✓ Passed**MOT #6** 2013-11-18 09:11**MOT test number** 165092023325**Result** ✓ Passed**MOT #5** 2012-11-29 11:02**MOT test number** 408264732455**Result** ✓ Passed**MOT #4** 2011-07-21 13:12**MOT test number** 317022901252**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)





MOT #3	2010-08-06 13:03
MOT test number	344018510459
Result	✓ Passed
MOT #2	2009-07-21 12:16
MOT test number	321952409490
Result	✓ Passed
MOT #1	2008-07-17 15:32
MOT test number	874049698119
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
8 April 2024

✓

MOT

Expires:  
3 January 2025

Tax status	Expired at 8 April 2024
Days left	21 days too late
MOT expiry date	3 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-07-12
Last registration	2024-01-04
Complete history	<a href="#">See info</a>



Registration #1	2005-07-12	11 mi
Registration #2	2008-07-17	21.450 mi
Registration #3	2009-07-21	25.298 mi
Registration #4	2010-08-06	30.649 mi
Registration #5	2011-07-21	36.314 mi
Registration #6	2012-11-29	42.671 mi
Registration #7	2013-11-18	48.617 mi
Registration #8	2014-11-03	51.980 mi
Registration #9	2015-11-02	55.627 mi
Registration #10	2015-11-03	55.627 mi
Registration #11	2016-11-08	58.698 mi
Registration #12	2016-11-08	58.698 mi
Registration #13	2016-11-08	58.698 mi
Registration #14	2016-11-08	58.698 mi
Registration #15	2016-11-08	58.698 mi
Registration #16	2016-11-08	58.698 mi
Registration #17	2016-11-08	58.698 mi
Registration #18	2016-11-08	58.698 mi
Registration #19	2016-11-08	58.698 mi
Registration #20	2016-11-08	58.698 mi
Registration #21	2016-11-08	58.698 mi
Registration #22	2016-11-08	58.698 mi
Registration #23	2016-11-08	58.698 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1825 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1371 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	5R43462