



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS TSI
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-03-22
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-18
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #15 2024-02-23 11:39

MOT test number 165062591861

Result ✓ Passed

Next expiry date 2025-03-18

Advice Offside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

MOT #14 2023-03-06 11:21

MOT test number 156853754350

Result ✓ Passed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Sidewall, 215/55/16 (5.2.3 (d) (i))

MOT #13 2022-03-19 11:36

MOT test number 517197513629

Result ✓ Passed

MOT #12 2021-07-16 12:05

MOT test number 502730057014

Result ✓ Passed

Advice Nearside Rear Nail in tyre

**MOT #11** 2020-08-11 10:35**MOT test number** 156028540061**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #10** 2019-05-30 11:48**MOT test number** 681474239815**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-06-18 15:18**MOT test number** 764923911884**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2017-06-07 11:24**MOT test number** 797373170929**Result** ✓ Passed**MOT #7** 2016-06-07 09:09**MOT test number** 646964896008**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Nearside Rear tyre inner edge odd wear pattern

**MOT #6** 2015-06-08 14:55**MOT test number** 576059755144**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-06-02 15:36**MOT test number** 457113254187**Result** ✓ Passed**MOT #4** 2013-06-04 12:54**MOT test number** 725335053100**Result** ✓ Passed**MOT #3** 2012-06-12 11:26**MOT test number** 718424062163**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in nearside rear tyre**MOT #2** 2011-06-01 10:27**MOT test number** 515242951149**Result** ✓ Passed**MOT #1** 2011-05-31 12:59**MOT test number** 697841251173**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
18 March 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KS08AYV
Plate since	2019-09-29
Current registration	 KS08AYV
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-09
Last registration	2024-02-23
Complete history	See info



Registration #1	2008-06-09	28 mi
Registration #2	2011-05-31	8.583 mi
Registration #3	2011-06-01	8.583 mi
Registration #4	2012-06-12	11.487 mi
Registration #5	2013-06-04	13.845 mi
Registration #6	2014-06-02	16.639 mi
Registration #7	2015-06-08	18.976 mi
Registration #8	2016-06-07	21.562 mi
Registration #9	2017-06-07	23.596 mi
Registration #10	2018-06-07	25.630 mi
Registration #11	2019-06-07	27.664 mi
Registration #12	2020-06-07	29.698 mi
Registration #13	2021-06-07	31.732 mi
Registration #14	2022-06-07	33.766 mi
Registration #15	2023-06-07	35.800 mi
Registration #16	2024-02-23	37.834 mi
Registration #17	2024-02-23	37.834 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

CAX 016127