





report date: 2024-03-29

#### General information

Make	VOLVO
Model	XC90 D5 POWERPULSE R-DESIGN PRO AWD
Colour	Black
Year of manufacture	2018
Top speed	137 mph
0 - 60 mph	7.4 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Fuel type  Consumption combined	Diesel 35.3 mpg
•	2.000



CarCheck.co.uk page 1/11



GD18UJT

report date: 2024-03-29

### Internet history

#### Entry 2

Date	2022-02-03
Pictures	1

Listing price <u>View report</u>




source: autoonline.co.uk

#### Entry 1

Date	2022-01-19
Pictures	5
Listing price	View report









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-26
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #5	2024-01-19 09:47
MOT test number	466604503084
Result	✓ Passed
Next expiry date	2025-01-26
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #4	2024-01-18 09:50
MOT test number	634899839636
Result	<b>X</b> Failed
Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3		2023-01-19 11:33
MOT test	number	951547121140
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



MOT #2 2022-01-27 15:15

MOT test number 178682175124

**Result** ✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2021-06-15 11:11

**MOT test number** 886244745459

**Advice** Covers fitted under vehicle

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords stones imbedded in

tread (5.2.3 (d) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge bald on outer edge (5.2.3 (e))

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	26 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



GD18UJT

report date: 2024-03-29

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	hictory
Owner	HISLOFY

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
PROPERTY.	
***********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	OK ON THE PROPERTY OF THE PROP
Plate since	
Current registration	NK NIA
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-06-30
Last registration	2024-01-19
Complete history	See info



Registration #1	2018-06-30	24 mi
Registration #2	2021-06-15	53.449 mi
Registration #3		11.777 es
Registration #4	2022-01-27	54.936 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



# Dimensions & weight

Width	2008 mm
Height	1776 mm
Length	4950 mm
Wheel base	2984 mm
Kerb weight	2009 kg
Max. allowed weight	2750 kg

## Additional information

Fuel tank capacity	71
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/1:

Number of axles2Engine number2551350