



AG09LDO

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Black
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-05-29
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2022-05-24
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	19
Total items failed	3

MOT #11	2021-05-25 11:04
MOT test number	398737552641
Result	✓ Passed
Next expiry date	2022-05-24
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2020-08-17 11:27
MOT test number	721040874977
Result	✓ Passed

MOT #9	2019-05-22 10:16
MOT test number	660331478125
Result	✓ Passed
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge and offside front inner (5.2.3 (e))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect and offside rear (5.3.2 (b))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #8	2018-05-17 14:37
MOT test number	867358325373
Result	✓ Passed

**MOT #7** 2017-05-08 14:07**MOT test number** 604485308705**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** N/S/F tyre valve perishing**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Both rear tyres perishing**MOT #6** 2016-05-17 11:14**MOT test number** 229659468100**Result** ✓ Passed**Advice** N/s/r tyre getting close limit**MOT #5** 2015-05-20 12:19**MOT test number** 187890945124**Result** ✓ Passed**Notice** N/s/r geting close to limit**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Front tyres geting close to legal limit**Notice** Front pads are geting low**Notice** Wishbone bushs starting to perish**MOT #4** 2014-05-27 16:24**MOT test number** 399587644140**Result** ✓ Passed**Notice** Nsr tyre close to limit



MOT #3	2013-05-31 10:41
MOT test number	286751753132
Result	✓ Passed
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2	2012-07-12 09:05
MOT test number	296274392488
Result	✓ Passed
Notice	Front under tray insecure

MOT #1	2012-07-12 09:05
MOT test number	567664092171
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Pass with rectification	Offside Headlamp aim too high (1.8)
Notice	Front under tray insecure



Tax & MOT check

X

Untaxed

Tax expired:
16 October 2021

X

MOT

Expired:
24 May 2022

Tax status	Expired at 16 October 2021
Days left	926 days too late
MOT expiry date	24 May 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AG09LDO
Plate since	2024-03-28
Current registration	 AG09LDO
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-07-17
Last registration	2021-05-25
Complete history	See info



Registration #1	2009-07-17	19 mi
Registration #2	2012-07-12	60.557 mi
Registration #3	2013-05-31	76.277 mi
Registration #4	2014-05-27	83.122 mi
Registration #5	2015-05-20	89.436 mi
Registration #6	2016-05-17	95.548 mi
Registration #7	2016-05-20	95.557 mi
Registration #8	2016-05-20	95.557 mi
Registration #9	2016-05-20	95.557 mi
Registration #10	2016-05-20	95.557 mi
Registration #11	2016-05-20	95.557 mi
Registration #12	2016-05-20	95.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CBD 106784