





report date: 2024-03-29

General information

Make	BMW
Model	316 316I SE
Colour	Silver
Year of manufacture	-
Top speed	128 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	175 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-09-05

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT #20		2020-10-01 15:04
MOT test	number	184849323530
Result		✓ Passed
Next expi	ry date	2021-09-30
Advice	Nearside Rear damage to wheel arch	
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Inner Suspension rod ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear oil leaking from differential	
Advice	Nearside Rear tyre wearing outer edge	
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front both front tyres wearing outer edge	

CarCheck.co.uk page 3/14



Advice

EU52GNX

report date: 2024-03-29

MOT #19		2020-09-18 12:27
MOT test	number	816171510844
Result		× Failed
Advice	Front both front tyres wearing outer edge	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
MAJOR	Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of	dirt (5.3.4 (b) (ii))
Advice	Rear oil leaking from differential	
Advice	Nearside Front Inner Suspension rod ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear tyre wearing outer edge	
MAJOR	Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear damage to wheel arch	
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #18		2019-09-23 15:42
MOT test	number	662117193259
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Differential oil leak	
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear damage to wheel arch	

Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/14



report date: 2024-03-29

✓ Passed

MOT #17 2018-08-17 15:02

MOT test number 781113245183

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened ns/os (1.1.14 (a) (ii))

MOT #16 2017-09-02 13:44

MOT test number 666611983158

Advice Oil leak at gearbox and sump

Advice Nearside Front Brake pad(s) wearing thin and o/s/f (3.5.1g)

MOT #15 2016-09-03 13:56

MOT test number 886782483262

Result ✓ Passed

Advice Brake pad(s) wearing thin all x4 (3.5.1g)

Result

MOT #14 2015-08-14 13:15

MOT test number 411746625747

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #13 2015-08-13 14:50 574058527270 **MOT** test number Result **X** Failed Fail Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2) Fail Nearside Front Brake hose excessively deteriorated (3.6.B.4d) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Offside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2) Fail Offside Front Brake hose excessively deteriorated (3.6.B.4d) **Fail**

MOT #12

MOT test number

126260944246

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Oil leak

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT test number

S57969743247

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Slight binding n/s/f caliper

Notice Under-trays fitted obscuring some underside components

Notice Oil leak

 MOT #10
 2012-09-18 15:11

 MOT test number
 759752162226

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #9

MOT test number

998441971237

Result

Notice Oil leak

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

2011-09-24 10:18 **MOT #8 MOT** test number 218697261295 Result **X** Failed Fail Nearside Rear Upper Brake pipe excessively corroded (3.6.B.2c) Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) Notice Suspension joint offside lower dust cover split/missing **Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Fail Nearside Headlamp aim too low (1.8) Fail Offside Rear Upper Brake pipe excessively corroded (3.6.B.2c) **Notice** Oil leak Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #7	2010-09-23 15:01
MOT test number	364206060409
Result	✓ Passed
Notice Front discs worn	
Notice Plastic sills	

CarCheck.co.uk page 7/14



Result

EU52GNX

report date: 2024-03-29

✓ Passed

2010-09-18 09:29 **MOT #6** 471321560205 **MOT** test number Result × Failed Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) Notice Front discs worn Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) **Notice** Plastic sills

 MOT #5
 2009-10-01 12:12

 MOT test number
 522664379286

 Result
 ✓ Passed

MOT #4 2008-09-30 11:29

MOT test number 912604478247

Result ✓ Passed

MOT #3 2008-09-27 11:33
MOT test number 894771678232

Result × Failed

Fail Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

 MOT #2
 2007-10-12 09:11

 MOT test number
 474405287250

MOT #1 2006-04-13 12:21
MOT test number 251783106423

Result ✓ Passed

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e when miscory		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report is		ve?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	NIK NIK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-09-01
Last registration	2020-10-01
Complete history	See info



Registration #1	2002-09-01	9 mi
Registration #2	2006-04-13	39.951 mi
Registration #3	2007-10-12	48.056 mi
Registration #4	2008-09-27	59.233 mi
Registration #5	2008-09-30	59.233 mi
Registration #6	2009-10-01	76.998 mi
Registration #7	2010-09-18	89.714 mi
Registration #8	2010-09-23	89.913 mi
Registration #9	2011-09-24	104.903 mi
Registration #10	2011-09-28	104.928 mi
Registration #11	2012-09-18	110.340 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		0.77 44

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1415 mm
Length	4471 mm
Wheel base	2725 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	63 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Engine number	A050G774

CarCheck.co.uk page 14/14