





report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO AUTHENTIQUE DCI 86
Colour	Blue
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-28


Internet history

Entry 1

Date 2021-05-24

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT #25 2023-11-02 17:00

MOT test number 127978532060

Result ✓ Passed

Next expiry date 2024-11-12

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #24 2022-11-02 17:29

MOT test number 862244728249

Result ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #23 2022-11-02 17:29

MOT test number 558601823123

Result X Failed

Pass with rectification Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #22 2021-11-10 11:04

MOT test number 787519787988

MOT #21 2020-11-13 13:43

MOT test number 778679839118

Result ✓ Passed

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #20 2020-11-12 09:34

MOT test number 385148419849

Result X Failed

Fail Nearside Front Inner Steering rack has excessive free play detected at the steering wheel (steering rack fitted) (2.3 (a) (i))

Fail Horn not working (7.7 (a) (ii))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #19 2019-05-24 13:33

MOT test number 234914186309

Result ✓ Passed

MOT #18 2019-05-24 07:52

MOT test number 486906173264

Result X Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Rear Seat belt not functioning as intended (7.1.2 (c))

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #17 2018-05-21 16:10

MOT test number 316996122830

Result

Passed

Advice Spare tyre defective

Advice Offside Play in steering rack inner joint(s)

Advice Rear exhaust hanger deteriorated

Advice Nearside Play in steering rack inner joint(s)

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #16 2018-05-21 08:41

MOT test number 404297965288

Result X Failed

Fail Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

Advice Nearside Play in steering rack inner joint(s)

Fail Nearside Front Position lamp not working (4.2.1 (a))

Minor Central Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))

Fail Nearside Headlamp aim not tested no beam pattern (4.1.2 (b))

Advice Nearside Front caliper dust cover deteriorated

Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Spare tyre defective

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Play in steering rack inner joint(s)

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Service brake excessively fluctuating (1.2.1 (e))

Advice Rear exhaust hanger deteriorated

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 5/15



NCO7WAU report date: 2024-03-28

MOT #15 2017-05-03 09:35

MOT test number 670290089069

Result ✓ Passed

Advice Nearside tie rod slight play

Advice Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

MOT #14 2017-05-02 11:01

MOT test number 938279146223

Result X Failed

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Advice Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

Advice Nearside tie rod slight play

Fail Nearside Front coil spring broken (2.4.C.1a)

Pass with rectification Offside Headlamp aim too low (1.8)

Fail Offside Stop lamp not working (1.2.1b)

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

MOT #13 2016-05-10 11:31

MOT test number 713146031994

Result

✓ Passed

MOT #12 2016-05-10 09:18

MOT test number 936979159514

Result X Failed

Advice Rear exhaust rubber deteriorated

Fail Nearside Steering arm has relative movement at its fixings (2.2.B.1h)

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #11

MOT test number

777993235192

Result

Notice Play in steering rack inner joint(s)

Advice Steering column top bearing slightly worn (2.1.2c)

MOT test number

Result

Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

Advice Steering column top bearing slightly worn (2.1.2c)

Fail Nearside Front coil spring broken (2.4.C.1a)

Fail Offside Rear wheel bearing rough when rotated (2.6.1)

MOT #9

MOT test number

Result

Advice Nearside Track rod end ball joint has slight play (2.2.B.1f)

Notice N/s/f brake caliper boot twisted

MOT test number

Result

Advice

Nearside Track rod end ball joint has slight play (2.2.B.1f)

Fail

Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Notice

N/s/f brake caliper boot twisted

Fail

Offside Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 7/15



Result

NC07WAU

report date: 2024-03-28

× Failed

MOT #7 2013-05-24 15:13

MOT test number 398354243144

Result ✓ Passed

MOT #6 2013-05-23 14:07

MOT test number 399473043127

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #5 2012-05-23 16:00

MOT test number 235864842116

Result ✓ Passed

MOT #4 2012-05-23 08:43

MOT test number 408974042147

Fail Nearside Rear Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2011-05-20 16:32

MOT test number 549340341184

Result ✓ Passed

MOT #2 2011-05-20 08:55

MOT test number 858870641179

Result X Failed

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

CarCheck.co.uk page 8/15



report date: 2024-03-28

MOT #1 2010-05-21 10:08

MOT test number 883431740141

Result ✓ Passed

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 9/15



NCO7WAU
report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

_	
Owner	history
OWITCH	HISCOLY

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

2000000	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NE UK
Plate since	
Current registration	UK UK
Flate since	m-0-0
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2007-05-31
Last registration	2023-11-02
Complete history	See info



Registration #1	2007-05-31	19 mi
Registration #2	2010-05-21	39.660 mi
Registration #3	2011-05-20	46.251 mi
Registration #4	2011-05-20	46.251 mi
Registration #5	2012-05-23	54.316 mi
Registration #6	2012-05-23	54.316 mi
Registration #7	2013-05-23	61.833 mi
Registration #8	2013-05-24	61.852 mi
Registration #9	2014-05-13	71.312 mi
Registration #10	2014-05-13	71.315 mi
Registration #11	2015-05-12	79.354 mi
Registration #12	2015-05-13	79.358 mi
Registration #13	2016-05-10	87.953 mi
Registration #14	2016-05-10	87.953 mi
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		71.777 es
Registration #20		71.777 es
Registration #21		71.777 esi
Registration #22		71.777 es
Registration #23		71.777 esi
Registration #24		71.777 es
Registration #25		11.777 es
Registration #26		11.777 es
CarCheck.co.uk		page 14/15

More info >



NCO7WAU report date: 2024-03-28

Car features

The RENAULT factory car options list is only available in the premium report.	
S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	

View the complete RENAULT factory list for this vehicle here.

More info >

Safety ratings

S0569

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2039 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Max. allowed weight	1745 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 15/15

Engine number

NOT KNOWN