



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC 136PS
Colour	Grey
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	319 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-15
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history****MOT #14** 2023-09-29 11:14**MOT test number** 755084771905**Result** ✓ Passed**Next expiry date** 2024-09-28**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #13** 2023-09-27 15:00**MOT test number** 867993395195**Result** ✗ Failed**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin Recommend Attention (1.1.13 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2022-05-14 17:06**MOT test number** 516401253151**Result** ✓ Passed

**MOT #11**

2021-03-13 11:37

**MOT test number**

688848986968

**Result**

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear exhaust heat shield insecure
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #10**

2021-03-06 09:56

**MOT test number**

631383121244

**Result**

✗ Failed

- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear exhaust heat shield insecure
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #9**

2020-03-06 14:26

**MOT test number**

423188097156

**Result**

✓ Passed

- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear exhaust heat shield insecure
- Advice** Under trays fitted preventing full inspection
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8**

2019-03-08 14:44

**MOT test number**

723012960202

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
- Minor** Rear Position lamp light intensity obviously reduced (4.2.3 (a) (i))

**MOT #7**

2018-03-07 13:28

**MOT test number**

683594248634

**Result**

✓ Passed

- Advice** Oil leak
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all round (3.5.1i)
- Advice** Coil spring corroded both rears (2.4.C.1b)

**MOT #6** 2018-02-22 10:13**MOT test number** 490033323852**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all round (3.5.1i)**Pass with rectification** Headlamp aim too high both fronts (1.8)**Advice** Coil spring corroded both rears (2.4.C.1b)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Oil leak**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #5** 2017-03-02 10:53**MOT test number** 408276030204**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Both rear tyres worn on inner edges**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #4** 2016-03-15 11:52**MOT test number** 154967215660**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2015-02-25 10:26**MOT test number** 866566555062**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2014-03-03 10:45**MOT test number** 597132164064**Result** ✓ Passed**MOT #1** 2013-03-08 15:37**MOT test number** 656237863042**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-18
Last registration	2023-09-29
Complete history	<a href="#">See info</a>



Registration #1	2010-03-18	23 mi
Registration #2	2013-03-08	40.517 mi
Registration #3	2014-03-03	59.592 mi
Registration #4	2015-02-25	73.472 mi
Registration #5	2016-03-15	88.028 mi
Registration #6	2017-03-02	101.368 mi
Registration #7	2018-02-22	111.519 mi
Registration #8	2018-03-07	111.703 mi
Registration #9	2019-03-07	111.703 mi
Registration #10	2019-03-07	111.703 mi
Registration #11	2019-03-07	111.703 mi
Registration #12	2019-03-07	111.703 mi
Registration #13	2019-03-07	111.703 mi
Registration #14	2019-03-07	111.703 mi
Registration #15	2019-03-07	111.703 mi
Registration #16	2019-03-07	111.703 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

AB89987