



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTi
Colour	Red
Year of manufacture	2001
Top speed	127 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-11
Pictures	3
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-06-29
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	30
Total items failed	9

MOT #222022-06-30 11:05

MOT test number362241368805

Result✓ Passed

Next expiry date2023-06-29

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Rear light lens damaged no white light showing

**MOT #21** 2022-06-30 11:05**MOT test number** 926384737867**Result** ✗ Failed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Rear light lens damaged no white light showing**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**MOT #20** 2021-06-18 12:06**MOT test number** 254589818183**Result** ✓ Passed**MOT #19** 2021-06-18 12:06**MOT test number** 280006136880**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #18** 2020-06-15 13:37**MOT test number** 199097233191**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Headlamp lens slightly defective Both front deteriorated lens (4.1.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge + cracking (5.2.3 (e))**MOT #17** 2020-06-15 09:19**MOT test number** 522786525756**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge + cracking (5.2.3 (e))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Headlamp lens slightly defective Both front deteriorated lens (4.1.1 (b) (i))**MOT #16** 2019-03-28 11:18**MOT test number** 794727931915**Result** ✓ Passed**MOT #15** 2018-04-24 10:26**MOT test number** 362827361347**Result** ✓ Passed**MOT #14** 2017-02-22 12:29**MOT test number** 771370878756**Result** ✓ Passed

**MOT #13** 2016-03-10 16:09**MOT test number** 877258974427**Result** ✓ Passed**MOT #12** 2015-02-27 10:32**MOT test number** 795798055063**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #11** 2014-03-06 15:36**MOT test number** 665195864002**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** General underbody corrosion**Notice** Under-trays fitted obscuring some underside components**Notice** Bonnet saftey catch faulty**MOT #10** 2013-03-07 11:45**MOT test number** 695916963039**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components

**MOT #9** 2013-03-07 09:27**MOT test number** 598846463029**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #8** 2012-03-08 09:49**MOT test number** 975338462063**Result** ✓ Passed**MOT #7** 2011-02-23 16:08**MOT test number** 196434051492**Result** ✓ Passed**MOT #6** 2010-03-04 12:34**MOT test number** 362023660042**Result** ✓ Passed**Notice** (1)rear no. plate starting to delaminate.(2)fr. & rear brake discs rusty.**MOT #5** 2009-03-04 16:57**MOT test number** 463653169016**Result** ✓ Passed**Advice** Front brake disc slightly pitted (3.5.1h)**MOT #4** 2009-03-04 15:01**MOT test number** 413473469098**Result** ✗ Failed**Advice** Front brake disc slightly pitted (3.5.1h)**Fail** Rear brake disc excessively pitted (3.5.1h)



MOT #3	2008-03-10 15:58
MOT test number	184150278071
Result	✓ Passed
MOT #2	2007-03-08 10:40
MOT test number	921727867090
Result	✓ Passed
MOT #1	2006-03-09 14:48
MOT test number	370448166085
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
20 November 2023

✕
MOT

Expired:
29 June 2023

Tax status	Expired at 20 November 2023
Days left	160 days too late
MOT expiry date	29 June 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2001-03-12
Last registration	2022-06-30
Complete history	See info



Registration #1	2001-03-12	11 mi
Registration #2	2006-03-09	38.726 mi
Registration #3	2007-03-08	46.272 mi
Registration #4	2008-03-10	52.288 mi
Registration #5	2009-03-04	54.770 mi
Registration #6	2009-03-04	54.770 mi
Registration #7	2010-03-04	55.725 mi
Registration #8	2011-02-23	57.175 mi
Registration #9	2012-03-08	58.789 mi
Registration #10	2013-03-07	60.027 mi
Registration #11	2013-03-07	60.027 mi
Registration #12	2014-03-06	61.133 mi
Registration #13	2015-03-06	61.133 mi
Registration #14	2015-03-06	61.133 mi
Registration #15	2015-03-06	61.133 mi
Registration #16	2015-03-06	61.133 mi
Registration #17	2015-03-06	61.133 mi
Registration #18	2015-03-06	61.133 mi
Registration #19	2015-03-06	61.133 mi
Registration #20	2015-03-06	61.133 mi
Registration #21	2015-03-06	61.133 mi
Registration #22	2015-03-06	61.133 mi
Registration #23	2015-03-06	61.133 mi
Registration #24	2015-03-06	61.133 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1ZZ0684744