



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Grey
Year of manufacture	2014
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-05-25
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-21
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	9
Total items failed	1

MOT #9 2023-06-13 11:21

MOT test number 645744240619

Result ✓ Passed

Next expiry date 2024-06-21

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Brake disc worn, but not excessively and o/s/f (1.1.14 (a) (i))

MOT #8 2022-06-22 09:54

MOT test number 127989231017

Result ✓ Passed

MOT #7 2022-06-22 07:57

MOT test number 373313219808

Result ✗ Failed

**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #6 2021-04-07 11:42

MOT test number 155203407618

Result ✓ Passed

**MOT #5** 2020-03-09 09:35**MOT test number** 197109751585**Result** ✓ Passed**Advice** Front Oil leak, but not excessive from engine (8.4.1 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #4** 2020-03-09 09:35**MOT test number** 640401407918**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Oil leak, but not excessive from engine (8.4.1 (a) (i))**MOT #3** 2019-04-03 08:03**MOT test number** 730806861656**Result** ✓ Passed**MOT #2** 2018-03-20 08:49**MOT test number** 690926312622**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #1** 2017-03-20 09:17**MOT test number** 202070075667**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
21 June 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	21 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 S13KRH
Plate since	2019-09-29
Current registration	 S13KRH
Plate since	2019-09-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-04-07
Last registration	2023-06-13
Complete history	<a href="#">See info</a>



Registration #1	2014-04-07	18 mi
Registration #2	2017-03-20	27.209 mi
Registration #3	2018-03-20	35.351 mi
Registration #4	2019-04-03	42.757 mi
Registration #5	2020-03-09	47.562 mi
Registration #6	2020-03-09	47.562 mi
Registration #7	2020-03-09	47.562 mi
Registration #8	2020-03-09	47.562 mi
Registration #9	2020-03-09	47.562 mi
Registration #10	2020-03-09	47.562 mi
Registration #11	2020-03-09	47.562 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 294843K LNQ