





report date: 2024-03-29

General information

Make	JAGUAR
Model	XJ XJ EXECUTIVE
Colour	Blue
Year of manufacture	2002
Top speed	140 mph
0 - 60 mph	8.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	316 Nm at 4.350 rpm
Engine capacity	3.248 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	31.0 mpg
Consumption combined	23.5 mpg
CO2 emission	290 g/km
CO2 label	М



CarCheck.co.uk page 1/15



Internet history


Entry 1

Date 2021-06-14


Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT	history
1.101	iliocol y

MOT expiry date	2025-01-31
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	38
Total items failed	4

MOT #23		2024-02-01 14:10
MOT test	number	765813232456
Result		✓ Passed
Next expi	ry date	2025-01-31
Advice	Nearside Rear Sub-frame pin or bush worn but not resulting in excessive	movement (5.3.4 (a) (i))
Advice Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))		gnificantly reduced (6.1.1
Advice	Offside Rear Sub-frame pin or bush worn but not resulting in excessive n	novement (5.3.4 (a) (i))

MOT #22	2023-02-01 12:34
MOT test number	313121865839
Result	✓ Passed
Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Underside and components rather corroded	

MOT #21	2022-01-18 14:06
MOT test number	815136689005
Result	✓ Passed

CarCheck.co.uk page 3/15



MOT #20 2022-01-13 13:23

MOT test number 381739648876

Result X Failed

MAJOR Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #19 2021-01-11 13:41

MOT test number 243819460175

MOT #18 2021-01-08 10:24

MOT test number 896948696263

Result X Failed

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #17 2020-01-14 15:04

MOT test number 683275314933

Result \rightarrow Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/15



MOT #16 2018-06-14 13:50

MOT test number 392307791627

Result ✓ Passed

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15 2018-06-05 14:50

MOT test number 689625066190

Result X Failed

MAJOR Nearside Front Tyre fouling a part of the vehicle (5.2.3 (f))

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MAJOR Offside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

DANGEROUS Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #14 2017-06-07 13:41

MOT test number 386881231628

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

CarCheck.co.uk page 5/15



MOT #13 2017-06-07 13:41

MOT test number 404440650168

Result X Failed

Advice Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Pass with rectification Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

MOT #12 2014-11-04 15:06

MOT test number 489698004426

Result \rightarrow Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11 2014-11-04 15:06

MOT test number 436168504364

Result X Failed

Pass with rectification Offside Steering rack gaiter insecure (2.2.D.2d)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Rear position lamp(s) not working (1.1.A.3b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2013-11-01 10:46

MOT test number 408275203456

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/15



MOT #9 2012-10-27 10:23

MOT test number 719901302309

Result
✓ Passed

MOT #8 2011-10-28 15:20

MOT test number 655101601333

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2011-10-28 10:31

MOT test number 857261301333

Result X Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2010-10-15 12:23

MOT test number 234868980297

MOT #5 2009-10-15 10:57

MOT test number 343458289211

MOT #4 2008-10-03 11:37

MOT test number 660837078289

Result ✓ Passed

CarCheck.co.uk page 7/15



MOT #3 2007-09-17 17:40

MOT test number 233970567259

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Power steering component(s) has slight seepage from a component (2.3.3b)

MOT #2 2006-09-05 16:05

MOT test number 474158146215

Result ✓ Passed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2005-11-23 12:14

MOT test number 130637225371

CarCheck.co.uk page 8/15



Tax & MOT check





Expires: 31 January 2025

Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		AR
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK C	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-01-22
Last registration	2024-02-01
Complete history	See info



Registration #1	2002-01-22	22 mi
Registration #2	2005-11-23	33.299 mi
Registration #3	2006-09-05	35.709 mi
Registration #4	2007-09-17	42.513 mi
Registration #5	2008-10-03	45.148 mi
Registration #6	2009-10-15	46.348 mi
Registration #7	2010-10-15	47.218 mi
Registration #8	2011-10-28	48.186 mi
Registration #9	2011-10-28	48.186 mi
Registration #10	2012-10-27	49.630 mi
Registration #11	2013-11-01	50.686 mi
Registration #12	2014-11-04	51.700 mi
Registration #13		11.177 mi
Registration #14		11.117 es
Registration #15		11.177 mi
Registration #16		11.117 es
Registration #17		11.177 mi
Registration #18		11.117 es
Registration #19		11.177 es
Registration #20		11.117 es
Registration #21		11.177 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		0.00 44

More info >



		_		
luma	nncinr	1C X.	MOIO	nt.
	ensior	אט כו	WEIG	HL

Width	1800 mm
Height	1320 mm
Length	5054 mm
Wheel base	2870 mm
Kerb weight	1710 kg

Additional information

Fuel tank capacity	81 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	KB0108141641

CarCheck.co.uk page 15/15