





report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE KNIGHT EDITION VVT
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-12-17

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-01-29
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #8		2023-01-30 16:21
MOT test	number	268881153314
Result		✓ Passed
Next expi	ry date	2024-01-29
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice (5.3.2 (b))	Nearside Rear Shock absorbers has slight external damage to the casir	ng Casing slightly corroded.
Advice Nearside Rear Tyre slightly damaged/cracking or perishing Cracks on outer edge and in tread. (5.2.3 (d) (ii))		
Advice	Offside Rear Nail in tyre	
Advice (5.3.2 (b))	Offside Rear Shock absorbers has slight external damage to the casing	Casing slightly corroded.
Advice tread. (5.2	Nearside Front Tyre worn close to legal limit/worn on edge At 3mm. Cra.3 (e))	acks on both edges and in

MOT #7		2021-09-21 09:45
MOT test	number	882606600640
Result		✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/12



Result

Advice

Advice

SA64ZHM

report date: 2024-03-28

MOT #6 2021-09-20 13:03

MOT test number 522371448736

Result

★ Failed

Passed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #5 2020-09-02 10:54

MOT test number 589928353561

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Offside Front Tyre slightly damaged/cracking or perishing Tyre slightly perishing (5.2.3 (d) (ii))

Nearside Rear Tyre slightly damaged/cracking or perishing Tyre slightly perishing (5.2.3 (d) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Tyre slightly perishing (5.2.3 (d) (ii))

MOT #4 2019-09-03 14:35

MOT test number 403287388582

Result

✓ Passed

MOT #3 2019-09-03 14:35

MOT test number 763742598913

Result X Failed

Pass with rectification Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2 2018-09-18 14:40

MOT test number 798779880379

Result ✓ Passed

Advice

Front Shock absorbers light misting of oil or has limited damping effect both front (5.3.2 (b))

MOT #1 2017-09-14 12:11

MOT test number 394373421530

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	29 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full re	

THE STATE OF THE S	

	More info >
· ·	
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Correct registration	NK SIE
Plate since	
Correct registration	NK SIE
Plate since	
	More info >
•	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-23
Last registration	2023-01-30
Complete history	See info



Registration #1	2014-09-23	9 mi
Registration #2	2017-09-14	4.904 mi
Registration #3	2018-09-18	11.094 mi
Registration #4	2019-09-03	17.106 mi
Registration #5	2019-09-03	17.106 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1808 mm
Height	1423 mm
Length	4312 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1746 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles2Engine numberD134963