



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Blue
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-23
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	26
Total items failed	0

MOT #15	2023-10-05 10:04
MOT test number	794787479992
Result	✓ Passed
Next expiry date	2024-10-23

MOT #14	2022-10-24 09:54
MOT test number	275299581363
Result	✓ Passed

MOT #13	2022-01-13 10:01
MOT test number	224238771932
Result	✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Fuel cap seal perishing.
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Side repeater flashing less than 60 times a minute (4.4.4 (a))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #12** 2021-01-20 09:46**MOT test number** 447757907691**Result** ✓ Passed**MOT #11** 2021-01-14 15:33**MOT test number** 757553369705**Result** ✗ Failed**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #10** 2020-05-08 10:58**MOT test number** 408689683606**Result** ✓ Passed**MOT #9** 2019-06-18 11:02**MOT test number** 506058535463**Result** ✓ Passed



## MOT #8

2019-06-17 15:06

MOT test number

390289168659

## Result

✗ Failed

**MAJOR** Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MAJOR** Nearside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MAJOR** Nearside Front Outer Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both front inner discs. (1.1.14 (a) (ii))

**MAJOR** Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MAJOR** Offside Front Upper Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MAJOR** Offside Front Headlamp aim too far to the right (4.1.2 (a))

## MOT #7

2018-06-06 14:57

MOT test number

562454445920

## Result

✓ Passed

## MOT #6

2018-06-04 14:00

MOT test number

119780823001

## Result

✗ Failed

**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MAJOR** Parking brake lever defective so that it cannot be satisfactorily operated no reserve travel (1.1.6 (d))

**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MAJOR** Nearside Front Headlamp insecure (4.1.1 (c))

## MOT #5

2017-06-09 09:02

MOT test number

570835044718

## Result

✓ Passed

**MOT #4** 2016-06-10 08:41**MOT test number** 615033107822**Result** ✓ Passed**MOT #3** 2015-05-28 13:54**MOT test number** 338638545119**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-06-16 13:35**MOT test number** 355197264118**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-06-19 13:38**MOT test number** 297250773495**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
23 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	23 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>YE10TWD</b>
Plate since	2019-03-29
Current registration	<b>YE10TWD</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-23
Last registration	2023-10-05
Complete history	<a href="#">See info</a>



Registration #1	2010-06-23	16 mi
Registration #2	2013-06-19	26.450 mi
Registration #3	2014-06-16	33.404 mi
Registration #4	2015-05-28	39.796 mi
Registration #5	2016-06-10	44.679 mi
Registration #6	2017-06-09	48.698 mi
Registration #7	2018-06-04	52.547 mi
Registration #8	2018-06-06	52.547 mi
Registration #9	2019-06-17	55.238 mi
Registration #10	2019-06-20	55.238 mi
Registration #11	2019-06-20	55.238 mi
Registration #12	2019-06-20	55.238 mi
Registration #13	2019-06-20	55.238 mi
Registration #14	2019-06-20	55.238 mi
Registration #15	2019-06-20	55.238 mi
Registration #16	2019-06-20	55.238 mi
Registration #17	2019-06-20	55.238 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Engine number	CGP 038843