





General information Make VAUXHALL Model COMBO 2300 L2H1 CDTI Colour White

| Year of | manufacture | |
|---------|-------------|--|

Gearbox

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 200 Nm at 1.500 rpm |
| Engine capacity | 1.248 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |

2013

5 speed Manual





Internet history

|--|

Date Pictures 2021-11-06

16

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-11-07 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 9 |
| Total items failed | 9 |

| MOT #11 | 2023-10-31 14:37 |
|--|------------------|
| MOT test number | 439858253247 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-07 |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i) |) |
| Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |



| FE13NUC | 1 |
|-------------------------|---|
| report date: 2024-03-29 | 9 |

| MOT #10 | 2023-10-27 08:49 |
|--|------------------|
| MOT test number | 873737399352 |
| Result | 🗙 Failed |
| FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |
| Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c) |)) |
| Fail Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii)) | |
| Fail Nearside Rear Outer Suspension component mounting prescribed area excessively of significantly reducing structural strength sill (5.3.6 (a) (i)) | corroded |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |
| Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b)) | |
| Fail Exhaust fumes entering cabin (6.1.2 (b) (i)) | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) | |
| Fail Offside Front Outer Seat belt anchorage prescribed area strength or continuity signification sill (7.1.1 (a) (i)) | ficantly reduced |

| МОТ #9 | 2022-10-29 08:56 | |
|--|------------------|--|
| MOT test number | 943955957987 | |
| Result | ✓ Passed | |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | | |
| MOT #8 | 2022-10-29 08:56 | |

| | | 2022 10 25 00.50 |
|--|--|------------------|
| MOT test number | | 450732030080 |
| Result | | 🗙 Failed |
| Pass with rectification | Offside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | | |





| MOT #7 | 2021-11-08 12:58 |
|---|------------------|
| MOT test number | 413527357290 |
| Result | ✓ Passed |
| | |
| МОТ #6 | 2021-03-23 15:07 |
| MOT test number | 437840224660 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2020-03-19 12:22 |
| MOT test number | 646605900376 |
| Result | Passed |
| | |
| MOT #4 | 2019-03-12 14:27 |
| MOT test number | 195518746006 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2018-03-23 11:45 |
| MOT test number | 637763388966 |
| Result | ✓ Passed |
| NoT "2 | 2017 02 24 10 25 |
| MOT #2 MOT test number | 2017-03-24 10:35 |
| | 649597856333 |
| Result | ✓ Passed |
| MOT #1 | 2016-03-04 11:29 |
| MOT test number | 190018573545 |
| Result | ✓ Passed |
| | • |
| Advice Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1) | |
| | |



Tax & MOT check

| √ Taxed | √ мот |
|------------------------------------|-----------------------------|
| Tax due: 1 December 2024 | Expires: 7 November 2024 |
| Tax status | Valid until 1 December |
| Days left | 215 |
| MOT expiry date | 7 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | FET O |
| Category | L AMP |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Category | AMPL |
| Туре | |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| AND | |
| | |
| | |
| ********** | |
| NUMBER OF CONTRACTOR OF CONTRA | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2013-03-26 |
| Last registration | 2023-10-31 |
| Complete history | See info |



| Registration #1 | 2013-03-26 | 16 mi |
|------------------|------------|------------|
| Registration #2 | 2016-03-04 | 52.326 mi |
| Registration #3 | 2017-03-24 | 68.822 mi |
| Registration #4 | 2018-03-23 | 86.359 mi |
| Registration #5 | 2019-03-12 | 103.151 mi |
| Registration #6 | 2020-03-19 | 119.667 mi |
| Registration #7 | 2021-03-23 | 132.831 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.117 mi |

More info >



Dimensions & weight

| Width | 2119 mm |
|---------------------|---------|
| Height | 1880 mm |
| Length | 4740 mm |
| Kerb weight | 1330 kg |
| Max. allowed weight | 2330 kg |
| | |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|---------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 2 |
| Engine number | 263A20004952810 LN9 |