




report date: 2024-03-28

General information

Make	AUDI
Model	RS4 RS4 AVANT FSI QUATTRO
Colour	Grey
Year of manufacture	2013
Top speed	155 mph
0 - 100 km/h	4.7 seconds
0 - 60 mph	4.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	331 kW / 451 HP / 444 BHP
Max. torque	430 Nm at 4.000 rpm
Engine capacity	4.163 cc
Cylinders	8
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	33.2 mpg
Consumption combined	26.4 mpg
CO2 emission	249 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-10-08
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-13
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #10	2023-11-14 08:58
MOT test number	239727235653
Result	✓ Passed
Next expiry date	2024-11-13
Advice	Rear Tyre worn close to legal limit/worn on edge On warning markers (5.2.3 (e))

MOT #9	2022-11-10 08:21
MOT test number	696034379951
Result	✓ Passed

MOT #8	2022-10-04 11:57
MOT test number	416250686947
Result	✗ Failed
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #7	2021-10-13 16:31
MOT test number	367164626061
Result	✓ Passed

**MOT #6** 2020-11-18 15:14**MOT test number** 513363432750**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #5** 2019-11-13 14:23**MOT test number** 341219238500**Result** ✓ Passed**MOT #4** 2018-11-23 12:25**MOT test number** 863078759650**Result** ✓ Passed**MOT #3** 2018-11-22 15:51**MOT test number** 300568052689**Result** ✗ Failed**Fail** Offside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure wall (5.2.3 (d) (ii))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2017-11-22 13:37**MOT test number** 363860763026**Result** ✓ Passed**MOT #1** 2016-11-24 11:28**MOT test number** 101751493005**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
13 November 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	13 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2023-03-28
Current registration	XXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-31
Last registration	2023-11-14
Complete history	See info



Registration #1	2013-05-31	6 mi
Registration #2	2016-11-24	27.921 mi
Registration #3	2017-11-22	30.314 mi
Registration #4	2018-11-22	32.694 mi
Registration #5	2018-11-23	32.693 mi
Registration #6	2019-11-13	35.820 mi
Registration #7	2019-11-20	35.820 mi
Registration #8	2019-11-20	35.820 mi
Registration #9	2019-11-20	35.820 mi
Registration #10	2019-11-20	35.820 mi
Registration #11	2019-11-20	35.820 mi
Registration #12	2019-11-20	35.820 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1416 mm
Length	4719 mm
Wheel base	2813 mm
Kerb weight	1770 kg
Max. allowed weight	2345 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

Engine number

CFSA013524