



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI S/S SPORTIVE
Colour	White
Year of manufacture	2015
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-09-15
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-17
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	21
Total items failed	7

MOT #12	2023-12-18 10:28
MOT test number	212786017044
Result	✓ Passed
Next expiry date	2024-12-17
Advice	Steering system slightly rough both top shock mount bearings (2.1.1 (a))
Advice	Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear exhaust box corroded

MOT #11	2023-12-18 10:28
MOT test number	489419887439
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear exhaust box corroded
Advice	Steering system slightly rough both top shock mount bearings (2.1.1 (a))
Advice	Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
Pass with rectification	Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #10** 2022-10-26 13:45**MOT test number** 916826951605**Result** ✓ Passed**Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #9** 2022-10-20 09:45**MOT test number** 858718871140**Result** ✗ Failed**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Steering system slightly rough (2.1.1 (a))**MOT #8** 2021-10-04 10:40**MOT test number** 254432648668**Result** ✓ Passed**MOT #7** 2021-10-01 14:11**MOT test number** 651419178765**Result** ✗ Failed**Fail** Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))

**MOT #6** 2021-04-16 09:44**MOT test number** 958619600802**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2021-04-16 09:44**MOT test number** 424525927282**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-01-31 10:18**MOT test number** 185754348575**Result** ✓ Passed**MOT #3** 2019-01-25 09:13**MOT test number** 854994411872**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2018-01-12 15:44**MOT test number** 714220524827**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2018-01-12 13:24
MOT test number	762853063406
Result	✗ Failed
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
17 December 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	17 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-01-26
Last registration	2023-12-18
Complete history	See info



Registration #1	2015-01-26	26 mi
Registration #2	2018-01-12	55.137 mi
Registration #3	2018-01-12	55.137 mi
Registration #4	2019-01-25	80.526 mi
Registration #5	2020-01-31	88.286 mi
Registration #6	2021-04-16	103.911 mi
Registration #7	2021-04-16	103.911 mi
Registration #8	2022-05-20	111.277 mi
Registration #9	2022-05-20	111.277 mi
Registration #10	2022-05-20	111.277 mi
Registration #11	2022-05-20	111.277 mi
Registration #12	2022-05-20	111.277 mi
Registration #13	2022-05-20	111.277 mi
Registration #14	2023-12-18	111.277 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1310 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	198A30007269701 LJ5