



BG55FTU

report date: 2024-03-29

General information

Make	MAZDA
Model	6 TS
Colour	Blue
Year of manufacture	-
Top speed	128 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	181 Nm at 4.100 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.2 mpg






Internet history

Entry 1

Date	2021-06-12
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #23	2022-10-25 13:41
MOT test number	638604781906
Result	✓ Passed
Next expiry date	2023-10-24

MOT #22	2022-10-14 14:25
MOT test number	489580832263
Result	✗ Failed
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
Fail	Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Fail	Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

MOT #21	2021-10-24 13:30
MOT test number	480975854819
Result	✓ Passed
Advice	Hand brake only just ret requirements=17%

MOT #20	2021-10-19 13:14
MOT test number	639065275638
Result	✗ Failed
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #19	2020-10-15 11:27
MOT test number	941720102143
Result	✓ Passed

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #18**

2020-09-30 11:13

MOT test number

266451402747

Result**✗ Failed****Advice** Offside Front Brake pipe corroded, covered in grease or other material to flex (1.1.11 (c))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Pre checks NO OIL on dipstick.....1 litre added to take up to min.**Fail** Nearside Rear Parking brake inoperative on one side offside rear low effort also. (1.4.1 (a))**Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn chalked (5.3.4 (a) (i))**Advice** Offside headlamp pattern deteriorated**Advice** Rear Child Seat fitted not allowing full inspection of adult belt 2 seats fitted**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**MOT #17**

2019-10-02 07:20

MOT test number

207564827014

Result**✓ Passed****Advice** Pre-checks no oil on dipstick 1 litre added**Advice** Offside headlamp pattern deteriorated.**Advice** Rear Child Seat fitted not allowing full inspection of adult belt nearside rear and offside rear**Advice** Items removed from driver's view prior to test**Advice** Pre-checks engine under tray insecure and hanging down. removed.**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2019-09-26 14:21

MOT test number

734855921073

Result**✗ Failed****Advice** Rear Child Seat fitted not allowing full inspection of adult belt nearside rear and offside rear**Fail** Offside Front Service brake lagging in operation (1.2.1 (d))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Front Brake hose excessively twisted fouling strut. (1.1.12 (b) (ii))**Advice** Pre-checks no oil on dipstick 1 litre added**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Items removed from driver's view prior to test**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Offside headlamp pattern deteriorated.**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Pre-checks engine under tray insecure and hanging down. removed.**MOT #15**

2018-10-03 09:02

MOT test number

346636932884

Result**✓ Passed****Advice** Rear Exhaust mounting defective back box bracket broken but still supported (6.1.2 (a))**Advice** Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Central general underbody corrosion

**MOT #14**

2018-10-02 09:05

MOT test number

321882730316

Result

✗ Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Exhaust mounting defective back box bracket broken but still supported (6.1.2 (a))**Advice** Central general underbody corrosion**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Fail** Rear Fuel tank leaking excessively or a risk of fire leaking from tank, unable to see where on the tank (6.1.3 (b) (ii))**MOT #13**

2017-10-05 09:10

MOT test number

808844517571

Result

✓ Passed

Advice Underbody general chassis and suspension corrosion**Advice** Nearside Front Front suspension has slight play in a track control arm inner bush and offside front (2.5.B.2b)**MOT #12**

2016-10-17 10:56

MOT test number

613099444824

Result

✓ Passed

Advice Nearside front brake flexi-hose slightly twisted**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #11**

2015-10-15 15:01

MOT test number

117261958835

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #10** 2015-10-15 08:46**MOT test number** 829897521434**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Offside Front Outer Steering retaining device missing track rod end split pin missing (2.2.C.1g)**Fail** Nearside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #9** 2014-10-15 15:58**MOT test number** 118098384222**Result** ✓ Passed**MOT #8** 2014-10-15 10:22**MOT test number** 416748384296**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #7** 2013-10-15 11:19**MOT test number** 929078883291**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-10-08 14:56**MOT test number** 216731283249**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Lower Suspension arm ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)



MOT #5	2012-10-05 08:56
MOT test number	975659472268
Result	✓ Passed
MOT #4	2011-10-03 09:40
MOT test number	126206771275
Result	✓ Passed
MOT #3	2010-10-05 14:09
MOT test number	690678870243
Result	✓ Passed
MOT #2	2009-09-24 08:46
MOT test number	720727269215
Result	✓ Passed
MOT #1	2008-10-06 11:00
MOT test number	332890388244
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-09-30
Last registration	2022-10-25
Complete history	See info



Registration #1	2005-09-30	19 mi
Registration #2	2008-10-06	26.241 mi
Registration #3	2009-09-24	33.973 mi
Registration #4	2010-10-05	39.589 mi
Registration #5	2011-10-03	45.001 mi
Registration #6	2012-10-05	52.606 mi
Registration #7	2013-10-08	61.194 mi
Registration #8	2013-10-15	61.203 mi
Registration #9	2014-10-15	71.729 mi
Registration #10	2014-10-15	71.729 mi
Registration #11	2015-10-15	78.510 mi
Registration #12	2015-10-15	78.510 mi
Registration #13	2016-10-17	86.519 mi
Registration #14	2016-10-17	86.519 mi
Registration #15	2016-10-17	86.519 mi
Registration #16	2016-10-17	86.519 mi
Registration #17	2016-10-17	86.519 mi
Registration #18	2016-10-17	86.519 mi
Registration #19	2016-10-17	86.519 mi
Registration #20	2016-10-17	86.519 mi
Registration #21	2016-10-17	86.519 mi
Registration #22	2016-10-17	86.519 mi
Registration #23	2016-10-17	86.519 mi
Registration #24	2016-10-17	86.519 mi
Registration #25	2016-10-17	86.519 mi



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1435 mm
Length	4690 mm
Wheel base	2675 mm
Kerb weight	1375 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 545778