



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT
Colour	Red
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





MOT history

MOT expiry date	2025-03-30
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	54
Total items failed	2

MOT #15	2024-03-19 13:22
---------	------------------

MOT test number	248160060441
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-30
------------------	------------

Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #14**

2024-03-14 12:03

**MOT test number**

627213906163

**Result****✗ Failed**

**MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**DANGEROUS** Central Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR** Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

**MOT #13**

2023-03-31 13:37

**MOT test number**

170124227145

**Result****✓ Passed**

**MOT #12** 2023-03-27 13:44**MOT test number** 994420372103**Result** ✗ Failed**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2022-03-03 12:29**MOT test number** 543470534506**Result** ✓ Passed**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2022-03-03 11:40**MOT test number** 516088121884**Result** ✗ Failed**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #9** 2020-10-19 15:59**MOT test number** 837939414125**Result** ✓ Passed**Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))

**MOT #8** 2020-10-19 12:39**MOT test number** 202016766688**Result** ✗ Failed

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))

**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #7** 2019-09-24 18:15**MOT test number** 302542291192**Result** ✓ Passed**MOT #6** 2018-07-12 15:07**MOT test number** 716142845763**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-07-12 15:07**MOT test number** 434396582709**Result** ✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #4** 2017-06-26 13:57**MOT test number** 813202820130**Result** ✓ Passed

- Advice** Front bumper insecure
- Advice** Offside outer sill damaged
- Advice** Undertrays fitted restricting full view of testable items
- Advice** Nearside Front inner wheel rim damaged
- Advice** Offside outer sill trim insecure

**MOT #3** 2016-06-20 13:17**MOT test number** 276021503615**Result** ✓ Passed**MOT #2** 2015-07-13 11:48**MOT test number** 825014995106**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Emissions registered zero at time of test
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1

2015-07-13 11:48

MOT test number

748204795192

Result

✗ Failed

Pass with rectification

Nearside Headlamp not working on dipped beam (1.7.5a)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)

Notice

Emissions registered zero at time of test

Notice

Engine covers fitted obscuring some components in the engine bay

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)

Notice

Under-trays fitted obscuring some underside components



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 April 2025

✓  
**MOT**  
  
Expires:  
30 March 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	30 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-07-18
Last registration	2024-03-19
Complete history	<a href="#">See info</a>



Registration #1	2012-07-18	26 mi
Registration #2	2015-07-13	35.171 mi
Registration #3	2016-06-20	50.789 mi
Registration #4	2017-06-26	69.179 mi
Registration #5	2018-07-12	83.091 mi
Registration #6	2018-07-12	83.091 mi
Registration #7	2019-09-24	89.413 mi
Registration #8	2020-10-19	95.458 mi
Registration #9	2020-10-19	95.458 mi
Registration #10	2020-10-19	95.458 mi
Registration #11	2020-10-19	95.458 mi
Registration #12	2020-10-19	95.458 mi
Registration #13	2020-10-19	95.458 mi
Registration #14	2020-10-19	95.458 mi
Registration #15	2020-10-19	95.458 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEF3023664