





report date: 2024-03-29

#### General information

Make	FIAT
Model	DUCATO 35 H/R P/V MULTIJET
Colour	White
Colour	Willie
Year of manufacture	2015
	02
Top speed	93 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	2.287 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	44.8 mpg
Consumption combined	40.4 mpg
CO2 emission	183 g/km
CO2 label	1



CarCheck.co.uk page 1/11



report date: 2024-03-29

### Internet history

### Entry 2

Date 2023-02-11

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-06-21

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



CE65ASU report date: 2024-03-29

MOT history

MOT expiry date	2024-09-04
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	8
Total items failed	0

MOT #8	2023-09-05 09:35
MOT test number	592406656500
Result	✓ Passed
Next expiry date	2024-09-04

MOT #7	2022-10-19 14:40
MOT test number	744952650941
Result	<b>✓</b> Passed

MOT #6	2022-10-18 13:35
MOT test number	646070448663
Result	<b>∨</b> Failed

**DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure inner side wall (5.2.3 (d) (ii))

MOT #5	2021-10-11 12:46
MOT test	number 699491195696
Result	✓ Passed
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2020-10-19 11:13 631743920287 **MOT test number** Result ✓ Passed MOT #3 2019-10-18 08:10 **MOT test number** 155245063359 Result ✓ Passed **Advice** Nearside Front Play in steering rack inner joint(s) **Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) **Advice** 

MOT #2

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #1	2018-10-09 14:26
MOT test number	673460006853
Result	✓ Passed

CarCheck.co.uk page 4/11



CE65ASU report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	4 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

_	
Owner	hictory
OWITEI	HIISLULY

·	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	
***************************************	
**************************************	
***************************************	
**************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK WIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-01
Last registration	2023-09-05
Complete history	See info



Registration #1	2015-09-01	19 mi
Registration #2	2018-10-09	47.361 mi
Registration #3	2019-09-30	69.356 mi
Registration #4	2019-10-18	70.643 mi
Registration #5	2020-10-19	90.890 mi
Registration #6	2021-10-11	108.057 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		D.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2050 mm
Height	2524 mm
Length	5998 mm
Kerb weight	1975 kg
Max. allowed weight	3500 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number Carcheck.co.uk	2292286 page 11/11