



report date: 2024-03-28

General information

| | |
|---------------------|-----------------------|
| Make | NISSAN |
| Model | MICRA IG-T N-CONNECTA |
| Colour | Red |
| Year of manufacture | 2018 |
| Top speed | 109 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 89 BHP |
| Max. torque | 140 Nm at 2.250 rpm |
| Engine capacity | 898 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 51.4 mpg |
| CO2 emission | 118 g/km |
| CO2 label | C |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-03-26 |
| Pictures | 11 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-01-11 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-20 |
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 11 |
| Total items failed | 1 |

| | |
|------------------|---|
| MOT #5 | 2024-01-15 16:15 |
| MOT test number | 505205015852 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-20 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|-----------------|--|
| MOT #4 | 2023-01-13 16:49 |
| MOT test number | 872641952163 |
| Result | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii)) |
| Advice | Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i)) |

**MOT #3** 2023-01-13 09:37**MOT test number** 651880361743**Result** ✗ Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Fail Offside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #2 2022-01-21 09:32**MOT test number** 884410599712**Result** ✓ Passed**MOT #1** 2021-03-25 09:00**MOT test number** 720431834307**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
20 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 20 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YD68FGN |
| Plate since | 2019-09-28 |
| Current registration | YD68FGN |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2018-09-29 |
| Last registration | 2024-01-15 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-09-29 | 17 mi |
| Registration #2 | 2021-03-25 | 14.020 mi |
| Registration #3 | 2022-01-21 | 15.737 mi |
| Registration #4 | | |
| Registration #5 | | |
| Registration #6 | | |
| Registration #7 | | |
| Registration #8 | | |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 79% |
| Pedestrian | 79% |
| Safety systems | 72% |
| Overall rating | 82% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1743 mm |
| Height | 1455 mm |
| Length | 3999 mm |
| Wheel base | 2525 mm |
| Kerb weight | 1066 kg |
| Max. allowed weight | 1510 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 41 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | D599611 |