



YT08FGJ

report date: 2024-03-29

General information

Make	BMW
Model	123 123D M SPORT
Colour	Grey
Year of manufacture	2008
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	201 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2024-07-05
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	26
Total items failed	7

MOT #16	2023-07-05 16:33
MOT test number	551165589168
Result	✓ Passed
Next expiry date	2024-07-05

MOT #15	2022-07-05 18:18
MOT test number	515429025580
Result	✓ Passed

MOT #14	2021-07-06 13:37
MOT test number	476030717625
Result	✓ Passed
Advice	Crack in windscreen

MOT #13	2020-01-14 16:59
MOT test number	831956425294
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Minor	Offside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

**MOT #12**

2020-01-14 12:15

MOT test number

588569234343

Result

✗ Failed

Minor Offside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #11**

2019-01-23 12:41

MOT test number

831127238315

Result

✓ Passed

Minor Brake hose slightly twisted both rear (1.1.12 (b) (i))**MOT #10**

2019-01-22 12:16

MOT test number

741288539403

Result

✗ Failed

Minor Brake hose slightly twisted both rear (1.1.12 (b) (i))**Fail** Nearside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Front Brakes imbalanced across an axle 35% (1.2.1 (b) (i))**MOT #9**

2018-01-10 15:20

MOT test number

246915212491

Result

✓ Passed

Advice Nearside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)

**MOT #8** 2018-01-08 14:14**MOT test number** 441520407917**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside rear brake recording little or no effort (3.7.B.5a)**Advice** Nearside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #7** 2017-02-01 12:12**MOT test number** 698271839302**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #6** 2016-02-26 09:37**MOT test number** 671354636429**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-03-17 10:43**MOT test number** 648116375005**Result** ✓ Passed

- Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Oil level on minimum

MOT #4 2014-03-15 10:20**MOT test number** 915974074075**Result** ✓ Passed

- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #3 2013-03-15 14:34**MOT test number** 348794773062**Result** ✓ Passed**MOT #2** 2012-03-02 11:38**MOT test number** 679212362073**Result** ✓ Passed



MOT #1	2011-02-24 10:58
MOT test number	426395751011
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Offside inner brake light bulb innop
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
5 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-06
Last registration	2023-07-05
Complete history	See info



Registration #1	2008-03-06	11 mi
Registration #2	2011-02-24	73.341 mi
Registration #3	2012-03-02	95.240 mi
Registration #4	2013-03-15	103.740 mi
Registration #5	2014-03-15	110.588 mi
Registration #6	2015-03-17	121.570 mi
Registration #7	2016-02-26	132.170 mi
Registration #8	2017-02-01	136.166 mi
Registration #9	2018-01-08	153.578 mi
Registration #10	2019-01-08	161.577 mi
Registration #11	2019-01-08	161.577 mi
Registration #12	2019-01-08	161.577 mi
Registration #13	2019-01-08	161.577 mi
Registration #14	2019-01-08	161.577 mi
Registration #15	2019-01-08	161.577 mi
Registration #16	2019-01-08	161.577 mi
Registration #17	2019-01-08	161.577 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1748 mm
Height	1423 mm
Length	4360 mm
Wheel base	2660 mm
Kerb weight	1495 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	93286766