




report date: 2024-03-29

General information

Make	HONDA
Model	CR-V I-DTEC EX
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg
CO2 emission	175 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-06-24
Pictures	26
Listing price	View report



source: [heycar.co.uk](#)



MOT history

MOT expiry date	2024-04-30
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #7	2023-04-25 14:16
MOT test number	604200931971
Result	✓ Passed
Next expiry date	2024-04-30

MOT #6	2022-04-19 13:44
MOT test number	303116691334
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2022-04-19 10:40
MOT test number	445181287967
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4**

2021-05-01 09:40

MOT test number

574843370298

Result

✓ Passed

- Advice** Nearside Front Nail in tyre
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3

2020-06-02 09:33

MOT test number

759187073931

Result

✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2

2018-10-29 17:26

MOT test number

124588286248

Result

✓ Passed

MOT #1

2017-10-25 13:10

MOT test number

752928113657

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
30 April 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	30 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-10-17
Last registration	2023-04-25
Complete history	See info



Registration #1	2014-10-17	15 mi
Registration #2	2017-10-25	39.123 mi
Registration #3	2018-10-29	43.427 mi
Registration #4	2020-06-02	48.427 mi
Registration #5	2021-05-01	52.328 mi
Registration #6	2022-05-01	55.328 mi
Registration #7	2022-05-01	55.328 mi
Registration #8	2022-05-01	55.328 mi
Registration #9	2023-04-25	58.328 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2095 mm
Height	1685 mm
Length	4570 mm
Wheel base	2630 mm
Kerb weight	1806 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N22B42114417