



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	5008 HDI ALLURE
Colour	Grey
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-06-25
Pictures	16
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-05-26
Pictures	16
Listing price	<a href="#">View report</a>



**AA** This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com

source: theaa.com



MOT history

MOT expiry date	2024-05-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	7
Total items failed	4

MOT #12	2023-05-03 09:58
MOT test number	555335772530
Result	✓ Passed
Next expiry date	2024-05-12

MOT #11	2023-05-03 08:21
MOT test number	681004556629
Result	✗ Failed
<b>Fail</b>	Offside Rear Brake pad(s) incorrectly mounted (1.1.13 (c))

MOT #10	2022-05-07 10:18
MOT test number	159999888439
Result	✓ Passed
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))



<b>MOT #9</b>	2022-05-07 10:18
<b>MOT test number</b>	497696656994
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

<b>MOT #8</b>	2021-05-13 11:05
<b>MOT test number</b>	402680199320
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2020-10-20 15:04
<b>MOT test number</b>	321021430019
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2020-10-16 10:56
<b>MOT test number</b>	959310208133
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Lower Suspension component ball joint excessively worn screws into hub type (5.3.4 (a) (i))
<b>Fail</b>	Brake disc significantly and obviously worn both front inner surfaces and webbing badly corroded (1.1.14 (a) (i))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

<b>MOT #5</b>	2019-10-16 10:14
<b>MOT test number</b>	245293039939
<b>Result</b>	✓ Passed



<b>MOT #4</b>	2018-10-18 10:17
<b>MOT test number</b>	303447768372
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Suspension arm ball joint has slight play acceptable slight vertical lift (5.3.4 (a) (i))

<b>MOT #3</b>	2017-10-10 09:11
<b>MOT test number</b>	989598424286
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2016-11-04 11:02
<b>MOT test number</b>	447637863873
<b>Result</b>	✓ Passed
<b>Advice</b>	Front brake disks worn and coroded

<b>MOT #1</b>	2015-11-16 16:39
<b>MOT test number</b>	226119302617
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
12 May 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	12 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-09-29
Current registration	<b>XXXXXX</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



## Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	15
<b>First mileage registration</b>	2012-10-08
<b>Last registration</b>	2023-05-03
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2012-10-08	12 mi
<b>Registration #2</b>	2015-11-16	21.987 mi
<b>Registration #3</b>	2016-11-04	32.375 mi
<b>Registration #4</b>	2017-10-10	42.682 mi
<b>Registration #5</b>	2018-10-18	55.164 mi
<b>Registration #6</b>	2019-10-16	65.442 mi
<b>Registration #7</b>	2020-10-16	70.399 mi
<b>Registration #8</b>	2020-10-20	70.399 mi
<b>Registration #9</b>	2021-05-03	75.356 mi
<b>Registration #10</b>	2021-10-16	80.313 mi
<b>Registration #11</b>	2022-05-03	85.270 mi
<b>Registration #12</b>	2022-10-16	90.227 mi
<b>Registration #13</b>	2023-05-03	95.184 mi
<b>Registration #14</b>	2023-10-16	100.141 mi
<b>Registration #15</b>	2024-03-28	105.098 mi

[More info >](#)



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1699 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

JBER3141583