



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 ALLURE COUPE CABRIOLET
Colour	Silver
Year of manufacture	2005
Top speed	116 mph
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-12-13
Pictures	21
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-26
MOT pass rate	52 %
MOT passed	15
Failed MOT tests	14
Total advice items	62
Total items failed	40

MOT #29	2023-11-27 13:58
MOT test number	704461679608
Result	✓ Passed
Next expiry date	2024-11-26
Advice	Fuel tank slightly loose strapping corroded (6.1.3 (a) (i))

MOT #28	2023-11-17 14:08
MOT test number	333810111968
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Fuel tank slightly loose strapping corroded (6.1.3 (a) (i))
Fail	Offside Rear Parking brake inoperative on one side (1.4.1 (a))



MOT #27

2022-11-18 11:24

MOT test number

783608812917

Result		✓ Passed
Advice	Offside slight play inner steering rack arm	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Minor	Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Central exhaust mounting broken	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice	Nearside Brake pipe corroded, covered in grease or other material under floor running from front to rear (1.1.11 (c))	

**MOT #26**

2022-10-31 11:26

**MOT test number**

764324981949

**Result****✗ Failed****Fail**

Nearside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice**

Offside play in inner steering arm joint

**Fail**

Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

**Fail**

Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice**

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice**

Brake pipe corroded, covered in grease or other material 2 pipes from front to back under n/s floor (1.1.11 (c))

**Minor**

Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

**Advice**

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Fail**

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Advice**

Central exhaust mounting broken

**Fail**

Nearside Front Passenger's seat backrest cannot be secured in the upright position. (6.2.6 (a) (i))

**Advice**

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Minor**

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #25**

2022-10-14 14:25

**MOT test number**

417198613031

**Result****✗ Failed**

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm and badly worn on inner edge secondary rubber exposed and ABOUT TO EXPOSE CORD! 205/45/16 87v (5.2.3 (e))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Fail** Nearside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure edge (5.2.3 (d) (ii))

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Nearside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**Advice** Brake pipe corroded, covered in grease or other material both underside brakes going from front to rear (1.1.11 (c))

**Fail** Offside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure edge (5.2.3 (d) (ii))

**Minor** Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #24**

2021-11-03 12:48

**MOT test number**

966690871118

**Result****✓ Passed**

**MOT #23** 2021-11-03 12:48**MOT test number** 989507566205**Result** ✗ Failed

**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #22** 2019-08-16 12:38**MOT test number** 427616107518**Result** ✓ Passed**MOT #21** 2019-08-14 07:38**MOT test number** 327024482840**Result** ✗ Failed

**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice** Centre exhaust mount broken but exhaust is still secure

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #20** 2018-09-05 14:59**MOT test number** 394318849445**Result** ✓ Passed

**Advice** Rear Upper Stop lamp(s) non-obligatory stop lamp not working high level lamp has some led's out (4.3.1 (a) (ii))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened ALL BRAKE DISCS CORRODING (1.1.14 (a) (ii))

**MOT #19**

2018-06-20 07:58

**MOT test number**

892982685805

**Result**

✗ Failed

**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively not clearing (3.4 (b) (ii))**Fail** Anti-lock braking system warning lamp indicates an ABS fault abs light on (1.6 (b))**Minor** Stop lamp(s) with a multiple light source up to 1/2 not functioning 40% of leds not working (4.3.1 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened All discs slightly corroded (1.1.14 (a) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively not clearing (3.4 (b) (ii))**MOT #18**

2017-05-23 08:17

**MOT test number**

652196306453

**Result**

✓ Passed

**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush Wishbone bush slight split (2.5.A.1c)**MOT #17**

2017-05-22 11:40

**MOT test number**

339681294403

**Result**

✗ Failed

**Fail** Offside Front Front suspension has excessive movement at a wishbone pin or bush Wishbone bush split (2.5.A.1c)**Fail** Nearside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush Wishbone bush slight split (2.5.A.1c)**MOT #16**

2016-03-23 13:00

**MOT test number**

398544053504

**Result**

✓ Passed



**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement BOTH BUSHES PERISHED (2.4.G.2)

**Advice** Offside Front Tyre worn close to the legal limit TREAD VERY LOW (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit TREAD VERY LOW (4.1.E.1)

**MOT #15** 2015-04-15 12:10**MOT test number** 238085205177**Result** ✓ Passed**MOT #14** 2015-04-13 16:47**MOT test number** 526443705172**Result** ✗ Failed

- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Front Suspension arm locating pin locking device not properly locked (2.4.G.3b)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front coil spring broken (2.4.C.1a)

**MOT #13** 2014-02-14 10:21**MOT test number** 499235044040**Result** ✓ Passed**MOT #12** 2014-02-14 08:19**MOT test number** 936805944011**Result** ✗ Failed

- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #11** 2013-03-26 09:51**MOT test number** 608645483033**Result** ✓ Passed

- Notice** N/s rear tyre perished and slight damage to outer sidewall

**MOT #10** 2012-03-29 12:46**MOT test number** 107669682098**Result** ✓ Passed**Notice** Front wiperblades smeary**Notice** N/s rear tyre perished**MOT #9** 2012-03-29 08:48**MOT test number** 128969382406**Result** ✗ Failed**Notice** Front wiperblades smeary**Fail** Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** N/s rear tyre perished**Notice** Nail in offside rear tyre**MOT #8** 2011-04-01 15:15**MOT test number** 667651891054**Result** ✓ Passed**MOT #7** 2011-04-01 09:15**MOT test number** 385561291080**Result** ✗ Failed**Fail** Offside Front Wheel bolt(s) missing (4.2.A.1e)**Fail** Nearside Front Wheel bolt(s) missing (4.2.A.1e)**MOT #6** 2010-04-13 15:17**MOT test number** 954763800105**Result** ✓ Passed



MOT #5	2010-04-12 15:44
MOT test number	201242100495
Result	✗ Failed
Advice	Offside Inner Track rod end ball joint has slight play (2.2.B.1f)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Advice	Rear brake disc slightly pitted (3.5.1h)

MOT #4	2009-09-01 14:15
MOT test number	381174249485
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Rear exhaust bracket corroded
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2009-08-26 15:03**MOT test number** 942548439202**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Rear exhaust bracket corroded**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #2** 2008-08-29 14:50**MOT test number** 322362648251**Result** ✓ Passed**Advice** Brake disc slightly pitted (3.5.1h)**MOT #1** 2008-08-28 11:20**MOT test number** 961981348292**Result** ✗ Failed**Fail** Nearside Front Lower Ball joint has excessive play (2.2.B.1f)**Notice** Nail in shoulder of osr tyre**Advice** Brake disc slightly pitted (3.5.1h)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
26 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	26 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	31
First mileage registration	2005-09-01
Last registration	2023-11-27
Complete history	<a href="#">See info</a>



Registration #1	2005-09-01	10 mi
Registration #2	2008-08-28	23.727 mi
Registration #3	2008-08-29	23.727 mi
Registration #4	2009-08-26	35.929 mi
Registration #5	2009-09-01	36.130 mi
Registration #6	2010-04-12	37.325 mi
Registration #7	2010-04-13	37.325 mi
Registration #8	2011-04-01	42.819 mi
Registration #9	2011-04-01	42.819 mi
Registration #10	2012-03-29	45.339 mi
Registration #11	2012-03-29	45.339 mi
Registration #12	2013-03-26	47.601 mi
Registration #13	2014-02-14	50.657 mi
Registration #14	2014-02-14	50.657 mi
Registration #15	2015-04-13	59.352 mi
Registration #16	2015-04-15	59.352 mi
Registration #17	2016-05-20	59.352 mi
Registration #18	2016-05-20	59.352 mi
Registration #19	2016-05-20	59.352 mi
Registration #20	2016-05-20	59.352 mi
Registration #21	2016-05-20	59.352 mi
Registration #22	2016-05-20	59.352 mi
Registration #23	2016-05-20	59.352 mi
Registration #24	2016-05-20	59.352 mi
Registration #25	2016-05-20	59.352 mi
Registration #26	2016-05-20	59.352 mi

Registration #27	2025-25-25	25,252 442
Registration #28	2025-25-25	25,252 442
Registration #29	2025-25-25	25,252 442
Registration #30	2025-25-25	25,252 442
Registration #31	2025-25-25	25,252 442

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1673 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1177 kg
Max. allowed weight	1572 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	FX7E2586857