



report date: 2024-03-28

General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Black
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-30
Pictures	1
Listing price	View report

AA

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com

source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2022-10-21
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	39
Total items failed	16

MOT #21	2021-10-22 05:36
MOT test number	302982224165
Result	✓ Passed
Next expiry date	2022-10-21

MOT #20	2020-08-08 08:33
MOT test number	158956999926
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2020-08-08 08:33
MOT test number	534377809213
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #18	2019-08-20 10:41
MOT test number	335343066465
Result	✓ Passed



MOT #17	2018-07-18 08:13
MOT test number	839376169165
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin all (1.1.13 (a) (ii))
Advice	Hand brake only just within limit

MOT #16	2017-07-06 13:50
MOT test number	212639129238
Result	✓ Passed
Advice	O/s/r tyre inner sidewall cut - not to cords
Advice	Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
Advice	Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
Advice	Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
Advice	Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #15**

2017-07-04 13:09

MOT test number

420676233786

Result**✗ Failed**

- Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** O/s/r tyre inner sidewall cut - not to cords
- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Fail** Rear fog lamp not working (1.3.2b)
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #14

2016-06-04 11:49

MOT test number

122853645390

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit inner edge BALD CLOSE TO CORDS BEING EXPOSED (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13**

2016-06-04 11:49

MOT test number

384254101651

Result

✗ Failed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit inner edge BALD CLOSE TO CORDS BEING EXPOSED (4.1.E.1)**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #12**

2015-06-01 11:55

MOT test number

975622955112

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #11**

2014-05-31 14:05

MOT test number

627751754147

Result

✓ Passed

MOT #10

2014-05-31 10:34

MOT test number

335261954152

Result

✗ Failed

Fail Rear fog lamp not working (1.3.2b)**Fail** Nearside Headlamp has a product on the light source so that the light output is severely reduced (1.7.5a)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #9** 2013-05-10 12:04**MOT test number** 509260633136**Result** ✓ Passed**MOT #8** 2013-03-12 14:07**MOT test number** 678811173002**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre also shows signs of cracking & perishing**MOT #7** 2013-03-11 12:33**MOT test number** 498730073018**Result** ✗ Failed**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Notice** Nail in nearside rear tyre**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #6** 2012-06-30 09:32**MOT test number** 935102982199**Result** ✓ Passed**Notice** Boot latch fault.**Notice** Wear on front brake disc inner faces.

**MOT #5** 2012-06-30 09:32**MOT test number** 639352082143**Result** ✗ Failed**Notice** Boot latch fault.**Pass with rectification** Nearside Headlamp aim too low (1.8)**Notice** Wear on front brake disc inner faces.**Pass with rectification** Rear fog lamp not working (1.3.2b)**MOT #4** 2011-06-30 09:31**MOT test number** 786671981166**Result** ✓ Passed**Notice** Advise left front wiper blade streaking**MOT #3** 2010-07-06 14:09**MOT test number** 274797180155**Result** ✗ Failed**Pass with rectification** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Notice** O/s/r tyre cracked with age.**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-07-06 14:09**MOT test number** 272677180189**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/r tyre cracked with age.



MOT #1	2009-09-19 09:29
MOT test number	993562969273
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
30 June 2021

✕
MOT

Expired:
21 October 2022

Tax status	Expired at 30 June 2021
Days left	1034 days too late
MOT expiry date	21 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-29
Last registration	2021-10-22
Complete history	See info



Registration #1	2006-09-29	16 mi
Registration #2	2009-09-19	14.854 mi
Registration #3	2010-07-06	17.945 mi
Registration #4	2011-06-30	25.188 mi
Registration #5	2012-06-30	33.081 mi
Registration #6	2013-03-11	39.167 mi
Registration #7	2013-03-12	39.171 mi
Registration #8	2013-05-10	39.208 mi
Registration #9	2014-05-31	47.779 mi
Registration #10	2014-05-31	47.780 mi
Registration #11	2015-06-01	51.979 mi
Registration #12	2015-06-01	51.979 mi
Registration #13	2015-06-01	51.979 mi
Registration #14	2015-06-01	51.979 mi
Registration #15	2015-06-01	51.979 mi
Registration #16	2015-06-01	51.979 mi
Registration #17	2015-06-01	51.979 mi
Registration #18	2015-06-01	51.979 mi
Registration #19	2015-06-01	51.979 mi
Registration #20	2015-06-01	51.979 mi
Registration #21	2015-06-01	51.979 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	19GK2653