



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE NAV
Colour	Black
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 3

Date	2023-12-12
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date	2022-02-09
Pictures	50
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-02-08
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-07
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #8	2023-12-08 17:48
MOT test number	164500799812
Result	✓ Passed
Next expiry date	2024-12-07

MOT #7	2022-09-19 09:39
MOT test number	773277922903
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Advice	Rear Inner Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

MOT #6	2021-10-27 12:48
MOT test number	551054092595
Result	✓ Passed

MOT #5	2020-10-08 13:50
MOT test number	761628778352
Result	✓ Passed
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement bush delaminating (5.3.4 (a) (i))

**MOT #4** 2020-10-07 08:49**MOT test number** 564761546552**Result** ✗ Failed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement bush delaminating (5.3.4 (a) (i))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #3 2019-04-05 15:27**MOT test number** 997345528804**Result** ✓ Passed**MOT #2** 2019-04-04 11:35**MOT test number** 938765323035**Result** ✗ Failed

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2018-04-09 11:01**MOT test number** 907381623030**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
7 December 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-11
Last registration	2023-12-08
Complete history	See info



Registration #1	2015-09-11	25 mi
Registration #2	2018-04-09	34.386 mi
Registration #3	2019-04-04	38.813 mi
Registration #4	2019-04-05	38.813 mi
Registration #5	2020-10-07	46.787 mi
Registration #6	2020-10-08	46.790 mi
Registration #7	2023-12-08	46.790 mi
Registration #8	2023-12-08	46.790 mi
Registration #9	2023-12-08	46.790 mi
Registration #10	2023-12-08	46.790 mi
Registration #11	2023-12-08	46.790 mi
Registration #12	2023-12-08	46.790 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1712 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	D4HAFZ094002
---------------	--------------