



NL56XTD

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 H/R P/V
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	285 Nm at 1.600 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT #17	2022-04-26 12:23
MOT test number	358245508950
Result	✓ Passed
Next expiry date	2023-04-25
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2021-04-23 15:25
MOT test number	890156090332
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2020-04-24 14:59
MOT test number	142871023895
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14**

2020-04-24 14:59

MOT test number

479076025372

Result**✗ Failed**

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #13

2018-10-22 14:35

MOT test number

715581762259

Result**✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12

2017-06-10 12:02

MOT test number

174681081286

Result**✓ Passed****MOT #11**

2016-06-03 09:06

MOT test number

449798680346

Result**✓ Passed**

**MOT #10** 2016-06-03 09:06**MOT test number** 131716278921**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #9** 2015-06-05 13:48**MOT test number** 679106055199**Result** ✓ Passed**Advice** Nearside Outer Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Outer Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #8** 2014-05-20 17:57**MOT test number** 315160844161**Result** ✓ Passed**Advice** Nearside Outer Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Outer Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #7** 2013-05-18 10:12**MOT test number** 427248433157**Result** ✓ Passed

**MOT #6** 2013-05-17 11:12**MOT test number** 245537933434**Result** ✗ Failed**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #5** 2012-05-18 10:36**MOT test number** 947739332124**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-05-19 17:12**MOT test number** 415599631119**Result** ✓ Passed**Notice** Damage to front end + both door mirror covers missing**Notice** Spare tyre defective**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #3** 2011-02-18 17:05**MOT test number** 915039541052**Result** ✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Headlamp aim too low (1.8)
- Fail** Offside Front Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
- Fail** An item not tested (Manual)
- Fail** Offside Front Body has a sharp edge caused by damage (6.1.C.1)
- Notice** Propshaft component defective
- Fail** Nearside Rear Stop lamp not working (1.2.1b)

MOT #2 2010-01-20 10:20**MOT test number** 631310420068**Result** ✓ Passed

- Advice** Front brake disc slightly pitted (3.5.1h)
- Advice** Nearside Front Drag link end ball joint has slight play (2.2.B.1f)
- Advice** Rear brake disc slightly pitted (3.5.1h)

MOT #1 2009-11-11 16:27**MOT test number** 582245019376**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Oil leak
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	NL56XTD
Plate since	2019-03-29
Current registration	NL56XTD
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-10-03
Last registration	2022-04-26
Complete history	See info



Registration #1	2006-10-03	15 mi
Registration #2	2009-11-11	68.199 mi
Registration #3	2010-01-20	68.466 mi
Registration #4	2011-02-18	101.017 mi
Registration #5	2011-05-19	106.674 mi
Registration #6	2012-05-18	111.038 mi
Registration #7	2013-05-17	125.728 mi
Registration #8	2013-05-18	125.729 mi
Registration #9	2014-05-20	138.678 mi
Registration #10	2015-05-20	151.577 mi
Registration #11	2016-05-20	164.476 mi
Registration #12	2017-05-20	177.375 mi
Registration #13	2018-05-20	190.274 mi
Registration #14	2019-05-20	203.173 mi
Registration #15	2020-05-20	216.072 mi
Registration #16	2021-05-20	228.971 mi
Registration #17	2022-04-26	241.870 mi
Registration #18	2023-04-26	254.769 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	2601 mm
Length	5680 mm
Kerb weight	2047 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	6P48961