



report date: 2024-03-29

General information

Make	DS
Model	DS3 PURETECH DSTYLE S/S
Colour	Black
Year of manufacture	2015
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history




Entry 2

Date	2021-12-28
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk

Entry 1

Date	2021-12-27
Pictures	41
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-04
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	33
Total items failed	7

MOT #9	2023-08-02 10:25
--------	------------------

MOT test number	467033300576
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-04
------------------	------------

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Outer edge damaged also wearing on inner edge (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**MOT #8**

2023-08-02 09:35

**MOT test number**

409928212861

**Result****✗ Failed**

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Outer edge damaged also wearing on inner edge (5.2.3 (d) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #7**

2022-08-02 12:12

**MOT test number**

590132052616

**Result****✓ Passed**

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))

**MOT #6** 2022-08-02 11:48**MOT test number** 697828236915**Result** ✗ Failed

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #5** 2021-07-27 09:57**MOT test number** 199413937217**Result** ✓ Passed**MOT #4** 2020-08-05 07:36**MOT test number** 505558426646**Result** ✓ Passed**MOT #3** 2019-09-11 12:52**MOT test number** 100524284833**Result** ✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #2** 2019-09-11 12:03**MOT test number** 277963989721**Result** ✗ Failed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #1** 2018-09-03 09:11**MOT test number** 311811897465**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
4 August 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	4 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this DS. See if, where and when this DS had damage and the car repair costs. We also check if this DS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra DS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this DS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this DS? How many owners did this DS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this DS had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this DS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this DS has been settled.

If not, and you buy this DS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this DS is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-14
Last registration	2023-08-02
Complete history	<a href="#">See info</a>



Registration #1	2015-09-14	15 mi
Registration #2	2018-09-03	15.948 mi
Registration #3	2019-09-11	27.011 mi
Registration #4	2019-09-11	27.011 mi
Registration #5	2020-08-05	32.967 mi
Registration #6	2021-07-27	42.151 mi
Registration #7	2023-08-02	42.151 mi
Registration #8	2023-08-02	42.151 mi
Registration #9	2023-08-02	42.151 mi
Registration #10	2023-08-02	42.151 mi
Registration #11	2023-08-02	42.151 mi
Registration #12	2023-08-02	42.151 mi

More info >



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2452 mm
Kerb weight	1070 kg
Max. allowed weight	1578 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	XV120130265