



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI DSG
Colour	Black
Year of manufacture	2009
Top speed	128 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-26
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-03
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	53
Total items failed	10

MOT #16	2023-11-04 11:52
MOT test number	555987539048
Result	✓ Passed
Next expiry date	2024-11-03
Advice	Rear Suspension arm corroded but not seriously weakened both side (5.3.3 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #15	2022-10-26 15:43
MOT test number	634535177786
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt

MOT #14	2022-10-20 11:39
MOT test number	874942310381
Result	✗ Failed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Front Windscreen wiper does not clear the windscreen effectively both wipers torn (3.4 (b) (ii))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt



MOT #13	2021-11-04 10:00
MOT test number	609928795456
Result	✓ Passed

MOT #12	2020-12-16 14:31
MOT test number	582310536863
Result	✓ Passed

- Advice** Covers fitted to floor pans inspection restricted
- Advice** Nearside Front level sensor damaged
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Engine under tray fitted inspection restricted of some components
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front level sensor damaged
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2019-12-12 16:09
MOT test number	574421322257
Result	✓ Passed

- Advice** Engine under tray fitted inspection restricted of some components
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Covers fitted to floor pans inspection restricted
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front adaptive suspension linkage /sensor arm broken seized

**MOT #10** 2019-12-12 10:42**MOT test number** 814378540952**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front adaptive suspension linkage /sensor arm broken seized
- Advice** Engine under tray fitted inspection restricted of some components
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Covers fitted to floor pans inspection restricted

MOT #9 2018-12-13 11:57**MOT test number** 305125409348**Result** ✓ Passed**MOT #8** 2018-12-12 11:05**MOT test number** 440395568710**Result** ✗ Failed

- Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Central Exhaust silencer slightly loose (8.1.1 (b) (i))

**MOT #7** 2017-11-29 12:01**MOT test number** 745791262124**Result** ✓ Passed

- Advice** Covers fitted to floor pans inspection restricted
- Advice** Central exhaust clamp/sleeve slightly corroded
- Advice** Engine under tray fitted inspection restricted of some components

MOT #6 2016-11-30 15:22**MOT test number** 899572235400**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)

MOT #5 2015-12-18 12:23**MOT test number** 180435670217**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc modified but not seriously weakened (3.5.1n)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc modified but not seriously weakened (3.5.1n)
- Advice** Offside Rear brake disc modified but not seriously weakened (3.5.1n)



MOT #4	2014-11-20 10:27
MOT test number	407764124472
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Covers fitted to floor pans
Notice	Under-trays fitted obscuring some underside components
Notice	Outer sill covers fitted

MOT #3	2014-11-20 10:27
MOT test number	465444924341
Result	✗ Failed
Notice	Outer sill covers fitted
Notice	Child seat fitted not allowing full inspection of adult belt
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Notice	Engine covers fitted obscuring some components in the engine bay
Pass with rectification	Offside Headlamp aim too high (1.8)
Notice	Covers fitted to floor pans
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Nearside Headlamp aim too high (1.8)



MOT #2	2013-11-22 14:01
MOT test number	727506623321
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components
Notice	Child seat fitted to nearside rear seat inspection restricted of adult seat belt

MOT #1	2012-11-27 10:07
MOT test number	537852232300
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
3 November 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SH59WNE
Plate since	2019-03-29
Current registration	 SH59WNE
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-11-30
Last registration	2023-11-04
Complete history	See info



Registration #1	2009-11-30	29 mi
Registration #2	2012-11-27	25.163 mi
Registration #3	2013-11-22	36.452 mi
Registration #4	2014-11-20	46.205 mi
Registration #5	2015-12-18	58.373 mi
Registration #6	2016-11-30	69.777 mi
Registration #7	2017-11-29	80.562 mi
Registration #8	2018-12-12	84.000 mi
Registration #9	2018-12-13	84.001 mi
Registration #10	2019-12-12	85.377 mi
Registration #11	2019-12-12	85.377 mi
Registration #12	2019-12-12	85.377 mi
Registration #13	2019-12-12	85.377 mi
Registration #14	2019-12-12	85.377 mi
Registration #15	2019-12-12	85.377 mi
Registration #16	2019-12-12	85.377 mi
Registration #17	2019-12-12	85.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1476 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 192068