





General information

Make	VAUXHALL
Model	MERIVA LIFE
Colour	Silver
Year of manufacture	2015
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 2

Date 2023-12-18

Pictures

10

Listing price

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-02-06

View report

15

PENTON 01202 238542

source: yesauto.com









MOT history

MOT expiry date	2024-12-18
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #9	2023-12-19 16:18
MOT test number	252933737005
Result	✓ Passed
Next expiry date	2024-12-18

MOT #8	2023-03-15 17:04	
MOT test number	291265037384	
Result	✓ Passed	
Advice Front Exhaust has a minor leak of exhaust gases flexi front pipe (6.1.2 (a))		
Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Minor Nearside Front Windscreen damaged but not adversely affecting driver's view chip in windscreen (3.2 (a) (i))		
Advice Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))		



MOT #7	2023-03-15 11:29	
MOT test number	322861910813	
Result	🗙 Failed	
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach to (5.2.3 (d) (i))	the ply or cords	
Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Minor Nearside Front Windscreen damaged but not adversely affecting driver's view chip in windscreen (3.2 (a) (i))		
Advice Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))		
Advice Front Exhaust has a minor leak of exhaust gases flexi front pipe (6.1.2 (a))		

MOT #6	2022-03-18 09:26
MOT test number	658520273037
Result	✓ Passed

MOT #5	2021-03-26 10:37
MOT test number	415223335888
Result	✓ Passed

MOT #4	2020-07-28 09:04
MOT test number	200239839949
Result	✓ Passed
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #3	2019-11-06 12:58
MOT test number	456079404571
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view chips (3.2 (a) (i))	





MOT #2		2019-11-06 12:58
MOT test number		391599965123
Result		🗙 Failed
Minor Windscreen dama	aged but not adversely affecting driver's view chips (3.2 (a) (i))	
Pass with rectificationNearside Front Headlamp aim projected beam image is obviously incorrect(4.1.2 (c))		sly incorrect
MOT #1		2018-11-02 10:22

MOT test number	286546295638
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 18 December 2024
Tax status	Valid until 1 January
Days left	247
MOT expiry date	18 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Correct registration	
Plate since	
	More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-11-30
Last registration	2023-12-19
Complete history	See info



Registration #1	2015-11-30	13 mi
Registration #2	2018-11-02	30.666 mi
Registration #3	2019-11-06	38.817 mi
Registration #4	2019-11-06	38.817 mi
Registration #5	2020-07-28	42.668 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.117 est

More info >





Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg
Additional information	
Additional information Fuel tank capacity	54
	54 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5