



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D SPORT
Colour	Silver
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D







Internet history

Entry 1

Date	2021-07-10
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-27
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	25
Total items failed	15

MOT #16	2023-06-26 10:23
MOT test number	915167132568
Result	✓ Passed
Next expiry date	2024-06-27

MOT #15	2022-06-28 12:29
MOT test number	471265732674
Result	✓ Passed
Advice	SUSPENSION AND UNDER BODY HAS AGE RELATED CORROSION

MOT #14	2021-06-28 15:05
MOT test number	314913610789
Result	✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside rear tyre stepped on inner edge

**MOT #13**

2021-06-21 08:45

MOT test number

977188631585

Result**✗ Failed**

- Fail** Rear Service brake excessively fluctuating Both (1.2.1 (e))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside rear tyre stepped on inner edge
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside wing mirror damaged
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12

2018-03-13 11:00

MOT test number

457464561435

Result**✓ Passed****MOT #11**

2018-03-13 11:00

MOT test number

696856137779

Result**✗ Failed**

- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)



MOT #10 2017-03-18 13:21

MOT test number 490892491424

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2017-03-18 11:20

MOT test number 858951186465

Result ✗ Failed

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2016-03-17 16:15

MOT test number 427654053305

Result ✓ Passed



MOT #7 2015-12-18 11:45

MOT test number 133437623260

Result ✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear perished

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear tyre nailed

Advice Nearside Front marker light inop

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2014-12-16 11:54

MOT test number 479650554371

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT #5 2014-12-16 11:54

MOT test number 195770954360

Result ✗ Failed

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

Notice Engine covers fitted obscuring some components in the engine bay

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Notice Under-trays fitted obscuring some underside components



MOT #4	2013-12-17 14:52
MOT test number	107971653342
Result	✓ Passed
MOT #3	2013-12-17 14:52
MOT test number	477131953305
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (1.8)
MOT #2	2012-12-21 11:40
MOT test number	698616352394
Result	✓ Passed
MOT #1	2012-01-04 12:31
MOT test number	195534302042
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
27 June 2024

Tax status		Valid until 1 March
Days left		306
MOT expiry date		27 June 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-10
Last registration	2023-06-26
Complete history	See info



Registration #1	2008-09-10	14 mi
Registration #2	2012-01-04	41.138 mi
Registration #3	2012-12-21	59.940 mi
Registration #4	2013-12-17	71.900 mi
Registration #5	2014-12-16	84.039 mi
Registration #6	2015-12-18	94.342 mi
Registration #7	2016-03-17	94.556 mi
Registration #8	2017-03-18	109.426 mi
Registration #9	2018-03-20	125.377 mi
Registration #10	2019-03-20	141.328 mi
Registration #11	2020-03-20	157.279 mi
Registration #12	2021-03-20	173.230 mi
Registration #13	2022-03-20	189.181 mi
Registration #14	2023-03-20	205.132 mi
Registration #15	2024-03-20	221.083 mi
Registration #16	2025-03-20	237.034 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1368 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	473928
---------------	--------