





report date: 2024-03-28

General information

| Make | VAUXHALL |
|---------------------|-------------------|
| Model | ASTRA SRI VX-LINE |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 134 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 148 BHP |
|-------------------------|---------------------|
| Max. torque | 245 Nm at 2.000 rpm |
| Engine capacity | 1.399 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.9 mpg |
| Consumption extra urban | 57.4 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 138 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2022-01-16


Pictures 24

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2022-01-13

Pictures 25

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

| MOT history |
|-------------|
|-------------|

| MOT expiry date | 2025-03-11 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 4 |
| Total items failed | 3 |

| MOT #5 | 2024-03-12 15:35 |
|------------------|------------------|
| MOT test number | 761261490411 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-11 |

| MOT test number 2985 Result | 94485420 |
|---|-----------------|
| Result | 54405420 |
| Result | X Failed |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Fail Brake performance unable to be tested (1.2.1 (g)) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |

| MOT #3 | 2023-11-16 10:12 |
|-----------------|------------------|
| MOT test number | 571419583702 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

430117544009

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

| MOT #1 | 2021-11-15 09:57 |
|-----------------|------------------|
| MOT test number | 190952748735 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 305 |
| MOT expiry date | 11 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | Н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Type

Date

Damage 2

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



-

BV68GWZ

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VAUXHALL had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2018-11-30 |
| Last registration | 2024-03-12 |
| Complete history | See info |



| Registration #1 | 2018-11-30 | 26 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-11-15 | 22.716 mi |
| Registration #3 | | 9.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 es |

More info >

CarCheck.co.uk page 10/11





report date: 2024-03-28

Safety ratings

| NCAP rating | **** | |
|----------------|-----------------|--|
| Adult | 86% | |
| Children | 84% | |
| Pedestrian | 83% | |
| Safety systems | 75% | |
| Overall rating | 83% | |
| Video | see crash video | |



Dimensions & weight

| Width | 1809 mm |
|---------------------|---------|
| Height | 1485 mm |
| Length | 4370 mm |
| Wheel base | 2662 mm |
| Kerb weight | 1203 kg |
| Max. allowed weight | 1820 kg |

Additional information

| Fuel tank capacity | 48 I | |
|--------------------|---------------------|--|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats | 5 | |
| Number of axles | 2 | |
| Engine number | B1182869HA6X0330LE2 | |

CarCheck.co.uk page 11/11