



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 T3 R-DESIGN
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.592 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	152 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-07-07
Pictures	3
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-06-27
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-01
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	28
Total items failed	8

MOT #13	2023-06-02 14:00
MOT test number	147430815726
Result	✓ Passed
Next expiry date	2024-06-01
Advice	Underbody tray fitted
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #12	2022-05-27 16:16
MOT test number	761752607418
Result	✓ Passed
Advice	Nearside Play in steering rack inner joint(s)
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #11	2021-05-12 14:25
MOT test number	754469661778
Result	✓ Passed
Advice	Advisory engine cover and under tray fitted

**MOT #10**

2021-05-12 09:46

MOT test number

404098615056

Result**✗ Failed**

Fail Tyre has a tear, caused by separation or partial failure of its structure nearside rear inner sidewall (5.2.3 (d) (ii))

Advice Advisory engine cover and under tray fitted

Fail Tyre has a tear, caused by separation or partial failure of its structure offside front inner sidewall (5.2.3 (d) (ii))

Fail Tyre has a tear, caused by separation or partial failure of its structure offside rear outer sidewall (5.2.3 (d) (ii))

MOT #9

2020-05-28 10:48

MOT test number

487191634249

Result**✓ Passed**

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8

2020-05-27 14:04

MOT test number

606919553602

Result**✗ Failed**

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Brake performance not tested (1.2.1 (g))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2019-01-21 12:54**MOT test number** 653557162561**Result** ✓ Passed**MOT #6** 2018-01-04 09:28**MOT test number** 310868686714**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Play in steering rack inner joint(s)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #5** 2017-02-01 14:18**MOT test number** 459581051251**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2017-02-01 10:09**MOT test number** 942209168256**Result** ✗ Failed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-01-25 12:10**MOT test number** 631400502836**Result** ✓ Passed**MOT #2** 2015-01-17 13:42**MOT test number** 355887115045**Result** ✓ Passed**MOT #1** 2014-01-08 14:16**MOT test number** 165788204067**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
1 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-25
Last registration	2023-06-02
Complete history	See info



Registration #1	2011-01-25	12 mi
Registration #2	2014-01-08	23.622 mi
Registration #3	2015-01-17	30.489 mi
Registration #4	2016-01-25	38.909 mi
Registration #5	2017-02-01	47.396 mi
Registration #6	2017-02-01	47.400 mi
Registration #7	2018-01-04	52.701 mi
Registration #8	2019-01-21	61.049 mi
Registration #9	2019-01-21	61.049 mi
Registration #10	2019-01-21	61.049 mi
Registration #11	2019-01-21	61.049 mi
Registration #12	2019-01-21	61.049 mi
Registration #13	2019-01-21	61.049 mi
Registration #14	2019-01-21	61.049 mi
Registration #15	2019-01-21	61.049 mi
Registration #16	2019-01-21	61.049 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1484 mm
Length	4028 mm
Wheel base	2775 mm
Kerb weight	1519 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1015993
---------------	---------