





report date: 2024-03-28

General information

Make	PEUGEOT
Model	BOXER HDI 335 L3 F/C
Colour	White
Year of manufacture	2015
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	32.5 mpg
CO2 emission	229 g/km
CO2 label	L



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-16

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-08
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	23
Total items failed	1

MOT #9		2024-02-09 14:13
MOT test	number	354103194413
Result		✓ Passed
Next expi	ry date	2025-02-08
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Power steering component has slight seepage from a component (2.1.5 (a))	
Advice	Nearside Rear Nail in tyre	
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Nearside Rear light cluster damaged	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	

CarCheck.co.uk page 3/12



MOT test number

Result

Advice

MAJOR

MAJOR

BN15LPA

report date: 2024-03-28

292291023668

× Failed

MOT #8 2024-02-06 09:48

Advice Nearside Rear Nail in tyre **MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **MAJOR MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Advice Nearside Rear light cluster damaged **Advice** Power steering component has slight seepage from a component (2.1.5 (a))

Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MAJOR Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Offside Front Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

 MOT #7
 2023-01-03 12:31

 MOT test number
 920328188926

Result
✓ Passed

MOT #6 2021-09-17 12:45

MOT test number 435929453819

CarCheck.co.uk page 4/12



BN15LPA

report date: 2024-03-28

MOT #5 2021-01-13 12:03

MOT test number 116660018894

MOT #4 2021-01-13 12:03

MOT test number 322311586333

Result × Failed

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #3 2019-07-12 11:09

MOT test number 570634532823

Result \rightarrow Passed

MOT #2 2019-07-12 10:30

MOT test number 567820862617

Result X Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1 2018-07-11 13:34

MOT test number 707304891481

Result \rightarrow Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



BN15LPA

report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

BN15LPA

report date: 2024-03-28

Owner history		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		JGEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		

More info >

UK UK

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-06
Last registration	2024-02-09
Complete history	See info



Registration #1	2015-03-06	15 mi
Registration #2	2018-07-11	13.219 mi
Registration #3	2019-07-12	16.914 mi
Registration #4	2019-07-12	16.924 mi
Registration #5	2021-01-13	21.949 mi
Registration #6	2021-01-13	21.949 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioni
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2050 mm
Height	2254 mm
Length	5963 mm
Kerb weight	1630 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Number of axles	2
Engine number Carcheck.co.uk	TRJA0841736 page 12/12