



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK350 SPORT
Colour	Silver
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 3.000 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.7 mpg
CO2 emission	244 g/km
CO2 label	L







Internet history

Entry 1

Date	2021-09-28
Pictures	27
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-03-09
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	44
Total items failed	12

MOT #19 2022-03-10 15:43

MOT test number 364542875105

Result ✓ Passed

Next expiry date 2023-03-09

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

MOT #18 2021-03-03 16:22

MOT test number 849468525360

Result ✓ Passed

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #17**

2021-02-18 09:41

MOT test number

300753896580

Result**✗ Failed**

- Advice** N/s/r indicator becoming pale
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Minor** Central Stop lamp(s) insecure (4.3.1 (c) (i))
- Advice** N/s/r coil spring becoming corroded
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Both headlamps becoming deteriorated
- Advice** Both rear tyres perishing at edges
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #16

2020-02-20 16:04

MOT test number

849119750237

Result**✓ Passed**

- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15**

2020-02-20 13:26

MOT test number

678191163710

Result

✗ Failed

- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #14

2019-02-19 14:16

MOT test number

556054214806

Result

✓ Passed

- Advice** Front headlight lenses in poor condition

MOT #13

2018-01-31 14:37

MOT test number

531882838266

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #12** 2018-01-30 12:12**MOT test number** 723736146137**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint arm (2.5.B.1a)**MOT #11** 2017-02-14 13:01**MOT test number** 603524563851**Result** ✓ Passed**Advice** Nearside Rear Seat belt stitching slightly frayed (5.2.2b)**Advice** Engine management light on**Advice** Both front tyres splitting on inner edge**MOT #10** 2017-02-14 11:23**MOT test number** 117458214993**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Engine management light on**Advice** Nearside Rear Tyre worn close to the legal limit on limit (4.1.E.1)**Advice** Both front tyres splitting on inner edge**Advice** Nearside Rear Seat belt stitching slightly frayed (5.2.2b)**MOT #9** 2016-02-11 10:07**MOT test number** 420633673600**Result** ✓ Passed

**MOT #8** 2015-02-13 11:02**MOT test number** 117964645441**Result** ✓ Passed**MOT #7** 2015-02-11 14:19**MOT test number** 107552745413**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2014-09-15 16:30**MOT test number** 327528554450**Result** ✓ Passed**Notice** Slight play nearside front wheel bearing**MOT #5** 2014-09-15 11:24**MOT test number** 209478354275**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Slight play nearside front wheel bearing

**MOT #4** 2013-09-04 14:23**MOT test number** 716177143238**Result** ✓ Passed**Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #3** 2012-09-01 11:21**MOT test number** 575475842241**Result** ✓ Passed**MOT #2** 2011-09-05 10:51**MOT test number** 667498841258**Result** ✓ Passed**MOT #1** 2008-10-15 11:43**MOT test number** 281319388283**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 FE55OWW
Plate since	2019-06-29
Current registration	 FE55OWW
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-05
Last registration	2022-03-10
Complete history	See info



Registration #1	2005-09-05	26 mi
Registration #2	2008-10-15	31.569 mi
Registration #3	2011-09-05	40.623 mi
Registration #4	2012-09-01	46.095 mi
Registration #5	2013-09-04	67.141 mi
Registration #6	2014-09-15	80.510 mi
Registration #7	2014-09-15	80.510 mi
Registration #8	2015-02-11	83.749 mi
Registration #9	2015-02-13	83.752 mi
Registration #10	2016-02-11	89.499 mi
Registration #11	2017-02-14	95.873 mi
Registration #12	2018-03-20	95.873 mi
Registration #13	2018-03-20	95.873 mi
Registration #14	2018-03-20	95.873 mi
Registration #15	2018-03-20	95.873 mi
Registration #16	2018-03-20	95.873 mi
Registration #17	2018-03-20	95.873 mi
Registration #18	2018-03-20	95.873 mi
Registration #19	2018-03-20	95.873 mi
Registration #20	2018-03-20	95.873 mi
Registration #21	2018-03-20	95.873 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1735 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27296030119232