



report date: 2024-03-28

General information

Make	HONDA
Model	CIVIC I-VTEC SE PLUS
Colour	Black
Year of manufacture	2014
Top speed	134 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	174 Nm at 4.300 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-13
Pictures	2
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-12-07
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	16
Total items failed	0

MOT #9	2023-11-30 11:56
MOT test number	500433999655
Result	✓ Passed
Next expiry date	2024-12-07
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #8	2022-11-18 15:12
MOT test number	609933399120
Result	✓ Passed
Advice	Vehicles internal headlight adjuster altered to recheck lights

MOT #7	2022-11-18 14:15
MOT test number	198508680429
Result	✗ Failed
DANGEROUS	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Vehicles internal headlight adjuster altered to recheck lights

MOT #6	2021-11-11 10:42
MOT test number	444158249977
Result	✓ Passed

**MOT #5** 2020-12-08 15:11**MOT test number** 944970456970**Result** ✓ Passed**Advice** Rear brake discs corroded**Advice** Engine covers / undertrays fitted**MOT #4** 2020-12-08 13:22**MOT test number** 936581557449**Result** ✗ Failed**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Engine covers / undertrays fitted**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Brake disc worn, pitted or scored, but not seriously weakened ALL (1.1.14 (a) (ii))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear wiper blade split**MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**MOT #3** 2019-05-07 09:12**MOT test number** 822279359890**Result** ✓ Passed**MOT #2** 2018-05-02 11:55**MOT test number** 407269806581**Result** ✓ Passed



MOT #1	2017-05-09 09:38
MOT test number	566631015223
Result	✓ Passed
Advice	Rear both tyres worn outer edges
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
7 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	7 December 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-05-30
Last registration	2023-11-30
Complete history	<a href="#">See info</a>



Registration #1	2014-05-30	10 mi
Registration #2	2017-05-09	50.924 mi
Registration #3	2018-05-02	63.984 mi
Registration #4	2019-05-07	75.289 mi
Registration #5	2020-12-08	85.593 mi
Registration #6	2020-12-08	85.593 mi
Registration #7	2023-11-30	85.593 mi
Registration #8	2023-11-30	85.593 mi
Registration #9	2023-11-30	85.593 mi
Registration #10	2023-11-30	85.593 mi
Registration #11	2023-11-30	85.593 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	83%
Pedestrian	69%
Safety systems	86%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2065 mm
Height	1470 mm
Length	4300 mm
Wheel base	2595 mm
Kerb weight	1339 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R18Z43023567