



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	ML ML 320 CDI EDITION 10
Colour	Black
Year of manufacture	-
Top speed	127 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	22.1 mpg
Consumption extra urban	36.2 mpg
Consumption combined	29.4 mpg



**MOT history**

MOT #13	2020-11-09 11:42
MOT test number	840832580273
Result	✓ Passed
Next expiry date	2021-11-12
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2019-11-08 11:28
MOT test number	709267003415
Result	✓ Passed

MOT #11	2019-11-01 14:33
MOT test number	807137093291
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #10	2018-10-25 14:36
MOT test number	252334405646
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2017-11-13 11:35**MOT test number** 503583347842**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #8** 2016-11-08 09:37**MOT test number** 196158247560**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2015-11-11 15:59**MOT test number** 737936273526**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured o/s n/s replace (1.4.A.2f)**Advice** F/r susp rusty/light corrosion some b/pipes/rack noisy rear 0/s n/s tyres well down**MOT #6** 2015-11-11 09:56**MOT test number** 609461864330**Result** ✗ Failed**Advice** Rear Direction indicator slightly discoloured o/s n/s replace (1.4.A.2f)**Advice** F/r susp rusty/light corrosion some b/pipes/rack noisy rear 0/s n/s tyres well down**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Nearside Stop lamp not working (1.2.1b)

**MOT #5** 2014-11-13 14:26**MOT test number** 446867214406**Result** ✓ Passed**MOT #4** 2014-11-12 12:03**MOT test number** 615316614339**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #3** 2013-05-20 12:05**MOT test number** 849400243101**Result** ✓ Passed**MOT #2** 2012-05-28 14:33**MOT test number** 287739742173**Result** ✓ Passed**MOT #1** 2011-05-20 12:52**MOT test number** 825780041113**Result** ✓ Passed



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	YF08NSO
Plate since	2019-03-29
Current registration	YF08NSO
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-05-28
Last registration	2020-11-09
Complete history	See info



Registration #1	2008-05-28	26 mi
Registration #2	2011-05-20	23.519 mi
Registration #3	2012-05-28	32.553 mi
Registration #4	2013-05-20	40.320 mi
Registration #5	2014-11-12	55.198 mi
Registration #6	2014-11-13	55.198 mi
Registration #7	2015-11-11	68.892 mi
Registration #8	2016-05-20	75.277 mi
Registration #9	2016-05-20	75.277 mi
Registration #10	2016-05-20	75.277 mi
Registration #11	2016-05-20	75.277 mi
Registration #12	2016-05-20	75.277 mi
Registration #13	2016-05-20	75.277 mi
Registration #14	2016-05-20	75.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1911 mm
Height	1815 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg
Max. allowed weight	2830 kg

Additional information

Fuel tank capacity	95 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	64294040672802